INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification












Scientific





ECO INSPECTION REPORT

India's Most Comprehensive And Scientific Vehicle Inspection Service



Vehicle Information

Make

Audi

Transmission Type


Automatic

Model	RS e-tron	Registration Type	Private
Year	2021	Registration No.	DL10CG3657
Trim	GT	VIN/Chassis Number	16191
Exterior Color	Grey	Kms Run	15025
Interior Color	Beige	Manufacturing Date	2021-05-20
Body Type	Sedan	Registration Date	2021-07-15
Fuel Type	Electric	Insurance Expiry	2022-7-14
Motor No.	452390	Location	Janak Puri
Number of Owners	1	Motor Sound Link	Listen Engine Sound

Key Highlights

Flood Damage	Νο	Insurance Copy Available	Νο
Tyre Life Remaining (KM)	25,105	Service Logs Available	Νο
Dent	Yes	Bank Hypothecation	Νο
Major Accidents	Yes	Bank NOC	Νο
RC Copy Available	Yes (Original)		

ECO Repair Estimate





support@eco.com




















Order ID : 20588 Generated : 12 Feb 2021

ECO OVERALL SCORE BREAKDOWN

Interior







Exterior



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 2/13










(a)



Order ID : 20588 Generated : 12 Feb 2021

EXTERIOR

Vehicle Exterior View and Condition



Front License Plate is available?	~
License Plates are HSRP complaint?	~
Head Lights are working?	~
Turn Signal lamps are working?	~
Hazard Lamps are working?	~

Rear License Plate is available?	~
HSRP colour sticker is available?	~
Tail Lights are working?	 Image: A start of the start of
Fog Lamps are working?	×
Break lights are working?	~





Rear windshield wiper is working in good condition?



Front windshield wiper is working in good condition?

Reverse parking lights are working?



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)









G Objective




G




Order ID : 20588 Generated : 12 Feb 2021


Exterior Images

FRONT VIEW





LEFT SIDE VIEW





RIGHT SIDE VIEW



LEFT FRONT CORNER VIEW



LEFT REAR CORNER VIEW



RIGHT FRONT CORNER VIEW



RIGHT REAR CORNER VIEW





support@eco.com





Page 4/13












Order ID : 20588 Generated : 12 Feb 2021

INTERIOR

Vehicle Interior View and Condition





Music System is working properly?	~
Navigation System is working properly?	~
Horn is loud & clear?	~
Sun Visors are working properly?	~
Luggage Compartment light is working properly?	N/A
Power Windows are working?	
Carpets are in good condition?	
Front Seat Belts are working properly?	N/A
Boot Lever is working properly?	
Front De-Fogger is available?	
USB port is available?	
Rear view mirror is functional?	
Passenger side seat adjustments are working properly?	 Image: A start of the start of

Speakers are working properly?	~
Steering Mounted Controls are working properly?	N/A
Handbrake is working properly?	~
All Cabin lights are working properly?	N/A
Central Lock is working?	×
Floor Mats are available?	~
Seat Covers are in good condition?	~
Rear Seat Belts are working properly?	N/A
Fuel Lid Lever is working properly?	~
Bonnet Lever is working properly?	~
Rear De-Fogger is available?	~
Glove box light is working?	~
Driver side seat adjustments are working properly?	~







support@eco.com





Page 5/13









G





Order ID : 20588 Generated : 12 Feb 2021

Interior Images


DASHBOARD VIEW




CLUSTER METER VIEW



FRONT SEATS



REAR SEATS



GLOVE BOX




INTERIOR REAR VIEW



INTERIOR FRONT VIEW



INTERIOR DOOR PANEL





support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)




Page 6/13




WHEELS

Wheel View and Condition



LEFT FRONT TYRE








support@eco.com






Page 7/13




ELECTRIC VEHICLE BATTERY, CHASSIS AND PERFORMANCE





BATTERY SPECIFICATIONS AND RECORDED DATA


Battery Type	Li-Ion
State of Charge (SoC) before Test Drive	85%
State of Charge (SoC) AfterTest Drive	75%
Battery Temperature	48 c
Battery Capacity	25 kwH
Test Drive Distance	5 Km
Average Discharge per Km Driven	2%






support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 8/13



Images

VIN/CHASSIS NUMBER





Documents

REGISTRATION CERTIFICATE




	one #: 9741474849	Cover Note #			Geographic	il Alea.		
	le Details & Premium C			_		Provide State	in a bia	
Registration Mark & No.	Year of Manut.	Type of Body Metallic	CC	Coverage	IDV in Rs.		ine No. 00222	- Seating C
140.		Make of Vehicle					ssis No.	
KA41N2842	2010	MARUTI ALTO LXI	796	Package	120861.00		89589	5
Registration Authori	ity							
Vehicle	Trailer	Non Electrical Access.	Elec./Elect. /	ADD.	BI-Fuel Kit	Total Value	Net Premiur	n Rs.
120861.00	0.00	0.00	0.00		0.00	120861.00	3295.92	
	A. Own Da	mage Premium(Rs.)	- 19			B. Third Party Premiu	um(Rs.)	
Fuel Kit (IMT 25)								
	ension (IMT 1) 10% (IMT 22A) 10) n (IMT 8)	S	0.0 -0.2 0.0	La La In Alies (IMT) PA Owner P Our price IMT 15 Less: Third Party P Limit of Liabi		20)		
ailies (IMT 31) oreign Vehicle Loadin leographical Area Ext railers (IMT 30) dditional Loading ess: roluntary Excess Less roll Theft Device (IMT utomobile Association landicap Discount (IM terricle Lise (IMT 13) to Claim Discount	ension (IMT 1) : 0% (IMT 22A) 10) n (IMT 8) IT 12)	(50%)	0.0 -89.2 0.0 0.0 0.0 -1939.3	A to Pale alies (IMT PA Owner PA Owner INT 15 Less: Third Party P Limit of Liabi	(10 Experience (IMT) ger (IMT 16) Still Ris 200000 I Area Extension (IMT roperty Damage (IMT Ity Under Section II-1 (I	20)		
ailies (IMT 31) oreign Vehicle Loadin leographical Area Ext railers (IMT 30) dditional Loading ess: oluntary Excess Less viti Theft Device (IMT utombile Association landicap Discount (IM fehicle Use (IMT 13)	ension (IMT 1) : 0% (IMT 22A) 10) n (IMT 8) IT 12)		0.0 -89.21 0.0 0.0 -1939.3 -678.7!	A to Pale alies (IMT PA Owner PA Owner INT 15 Less: Third Party P Limit of Liabi	(ao Españo) (IMT) ger (IMT 16) Still Res 200000 I Area Extension (IMT roperty Damage (IMT)	20)		

INSURANCE COPY



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 9/13







Comprehensive Objective

G

C






Order ID : 20588 Generated : 12 Feb 2021

NEED ATTENTION

Interior





Central Lock Not Working Remarks

Repair Estimate ₹600








Power Window Not Working

Repair Estimate ₹600


Remarks

Wheel











Repaired: Color Mismatched, Color faded, Visible dent, Misaligned

₹NA



support@eco.com





Page 10/13







Objective Comprehensive

G

G





Generated : 12 Feb 2021 Order ID : 20588

Other Images

GRILLE



FRONT BUMPER



REAR BUMPER



BONNET HOOD




FRONT WINDSHIELD



REAR WINDSHIELD





LEFT FENDER







LEFT QUARTER PANEL





support@eco.com





Page 11/13





Unbiased

G Comprehensive Objective

G





Order ID : 20588 Generated : 12 Feb 2021

Other Images

RIGHT QUARTER PANEL



BOOT TRUNK LID



ROOF



FRONT LICENSE PLATE



CED **APLE** RS m-tr 0 0

REAR LICENSE PLATE



ODOMETER



POWER WINDOWS



REAR VIEW MIRROR



ENGINE COMPARTMENT



UNDERCARRIAGE



BATTERY



TRUNK LID





support@eco.com





Page 12/13









C





Order ID : 20588 Generated : 15 Jul 2022

Other Images

MIL/ENGINE LIGHT



Overall Comments

Car is in average condition

Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the


mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)




Page 13/13











www.droom.in/eco