

Pankaj
Ordered By

203682
Order ID

06 Sep 2022
Generated on

Gurgaon
Location

Vehicle Health Report

121+ Checkpoints Based Smart Engine Diagnosis

BMW X3 2018, XDRIVE 30I LUXURY LINE



Fuel Type	Petrol	Engine CC	1200
Transmission	Automatic	Kms Run	16000
Insurance	Valid	Service Logs Available	NA
Registration Number	DND0001	Engine Sound Link	Click Here

Vehicle Summary



The Overall Health of this vehicle is in
Good Condition









Approximate Expense

₹ 5,700

Your vehicle Needs attention on **Engine Misfire, Back Compression, Wheel Balancing, Bumpers, Fenders & Quarter Panels.**

Benchmarking & Comparison with similarly aged vehicles

Current Vehicle Age: **3.0 years**

Sections	Section Score	Ideal score for similar aged Vehicle	Median score for similar aged vehicle	Remarks
 Engine, Transmission & Chassis		7.5 - 8.5	0	Your vehicle's Engine, Transmission & Chassis has witnessed normal wear and tear"
 Tyres		6.5 - 7.5	8	Great! Your vehicle's Tyres has witnessed less wear and tear than usual
 Interior		7.5 - 8.5	7.88	Your vehicle's Interior has witnessed more wear and tear than usual
 Exterior		8 - 9	7.61	Your vehicle's Exterior has witnessed normal wear and tear"
 AC Performance		7.5 - 8.5	0	Your vehicle's AC Performance has witnessed normal wear and tear"



NEED ATTENTION

Interior

PEDAL BOOT CONDITION



Remarks Major Wear & Tear
Repair Estimate ₹ 5000

Exterior

EXTERIOR HSRP COLOUR STICKER



Remarks HSRP colour sticker is not available
Repair Estimate ₹ 600

EXTERIOR REAR WINDSHIELD WIPER



Remarks Rear windshield wiper is not working or is damaged
Repair Estimate ₹ 100




Engine, Transmission & Chassis

Test Drive and Condition



Vehicle Hood View and Condition



Hood Images

ENGINE COMPARTMENT




UNDERCARRIAGE




WHEELS

Wheel View and Condition



Wheel Images



INTERIOR

Vehicle Interior View and Condition



Reverse Parking Camera

8

Reverse Parking Sensors

NA

Door Hinges

8

Front LH Door Panel

8

AC Performance

8

Rear LH Door Panel

8

8 Ceiling

8 Dashboard & Instrument Panel

10 Odometer

8 Front RH Door Panel

NA Heating System

4 Pedals

8 Rear RH Door Panel

Music System is working properly?



Navigation System is working properly?



Horn Sound is working?



Handbrake is working properly?



All Cabin lights are working properly?



Central Lock is working?



Floor Mats are available?



Front Seat Covers are in good condition?



Rear Seat Covers are in good condition?



Rear Seat Belts are working properly?



Passenger side seat adjuster is working properly?



Bonnet Lever is working properly?



Rear De-fogger is available?



Glove Box light is working?



Rear View Mirror is functional?



Speakers are working properly?



Steering Mounted Controls are working properly?



Odometer/Trip switches are working properly?



Sun Visors are working properly?



Luggage Compartment light is working properly?



Power Windows are working?



Carpets are in good condition?



Front Seat Belts are working properly?



Driver side seat adjuster is working properly?



Fuel Lid Lever is working properly?



Boot Lever is working properly?



Front De-fogger is working properly?



USB port is available?



Interior Images

DASHBOARD VIEW



CLUSTER METER VIEW



FRONT SEATS



REAR SEATS



GLOVE BOX



INTERIOR REAR VIEW



INTERIOR FRONT VIEW




INTERIOR DOOR PANEL



EXTERIOR

Vehicle Exterior View and Condition



Front License Plate is in Good Condition?	✓
License Plates are HSRP compliant?	✓
Head Lights are working in Good Condition?	✓
Turn Signal lamps are working in Good Condition?	✓
Hazard Lamps are working?	✓
License Plate Light is working in Good Condition?	✓
Rear Windshield Wiper is working in good condition?	✗

Rear License Plate is in Good Condition?	✓
HSRP colour sticker is available?	✗
Tail Lights are working in Good Condition?	✓
Fog Lamps are working in Good Condition?	✓
Brake Lights are working in Good Condition?	✓
Front Windshield Wiper is working in good condition?	✓
Reverse Parking lights are working in Good Condition?	✓



Exterior Images

FRONT VIEW



REAR VIEW



LEFT SIDE VIEW



RIGHT SIDE VIEW



LEFT FRONT CORNER VIEW



LEFT REAR CORNER VIEW



RIGHT FRONT CORNER VIEW



RIGHT REAR CORNER VIEW



Miscellaneous

Airbags are available?



VIN/Chassis Number matching with document?

N/A

Vehicle Jack & wrench available?



Cruise Control is available?



Medical Kit available?



MIL/Engine Light is OFF?



Other Images

HOOD ENGINE OIL LEVEL



HOOD BATTERY



HOOD WIRING



WHEEL FRONT LH TYRE



WHEEL FRONT RH TYRE



WHEEL REAR LH TYRE



WHEEL REAR RH TYRE



WHEEL SPARE TYRE



INTERIOR FRONT LH DOOR PANEL



INTERIOR FRONT RH DOOR PANEL



INTERIOR REAR LH DOOR PANEL



REAR RH DOOR PANEL



DASHBOARD & INSTRUMENT PANEL



REVERSE PARKING CAMERA



PEDAL BOOT CONDITION?



Other Images

INTERIOR NAVIGATION SYSTEM



INTERIOR STEERING MOUNTED CONTROLS



INTERIOR CENTRAL LOCK



INTERIOR POWER WINDOWS



INTERIOR FLOOR MATS



INTERIOR REAR DE-FOGGER



INTERIOR USB PORT



INTERIOR REAR VIEW MIRROR



EXTERIOR GRILLE



EXTERIOR FRONT BUMPER



EXTERIOR BONNET / HOOD



EXTERIOR FRONT WINDSHIELD



EXTERIOR LH FENDER



EXTERIOR LH SIDE MIRROR



EXTERIOR LH FRONT DOOR



Other Images

EXTERIOR LH REAR DOOR



EXTERIOR LH QUARTER PANEL



EXTERIOR REAR BUMPER



EXTERIOR BOOT / TRUNK LID



EXTERIOR REAR WINDSHIELD



EXTERIOR RH QUARTER PANEL



EXTERIOR RH REAR DOOR



EXTERIOR RH FRONT DOOR



EXTERIOR RH SIDE MIRROR



EXTERIOR RH FENDER



EXTERIOR ANTENNA



EXTERIOR ROOF



EXTERIOR FRONT LICENSE PLATE



EXTERIOR REAR LICENSE PLATE



EXTERIOR HSRP COLOUR STICKER



Other Images

EXTERIOR FRONT WINDSHIELD WIPER



EXTERIOR REAR WINDSHIELD WIPER



VIN / CHASSIS NO MATCHING



MIL/ENGINE LIGHT



MISCELLANEOUS CRUISE CONTROL



Overall Comments

NA

Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology Limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

