

# INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification



Independent




Unbiased



Objective



Comprehensive



Scientific

- a service by **droom**

# ECO INSPECTION REPORT

India's Most Comprehensive And Scientific Vehicle Inspection Service

## Ordered By




Anant Goel

 10 / 01 / 2021

 Gurgaon

## Inspected By




Mitesh Karwa

 Verified Technician

 36+ Vehicle Inspected

 4+ Years Experience

## Audi A4 Premium Plus, 2019



## Vehicle Information


Make	Audi	Registration Number	983463
Model	A4	VIN/Chassis Number	25105
Year	2019	Engine Number	MH4365SD
Trim	Premium Plus	Engine CC	200
Exterior Color	Terra Gray	Insurance Expiry	2021-07-14
Interior Color	Beige	Registration Date	2019-7-14
Body Type	Sedan	Manufacture Date	2018-5-11
Fuel Type	Petrol	Location	Gurgaon
Transmission Type	Automatic	CNG Validity	NA
Kilometres Run	1234567	Engine Sound Link	<a href="#">Listen Engine Sound</a>





## Key Highlights

Flood Damage	No	Insurance Copy Available	No
Tyre Life Remaining (KM)	25,105	Service Logs Available	No
Dent	Yes	Bank Hypothecation	No
Major Accidents	No	Bank NOC	No
RC Copy Available	Yes (Original)		

## ECO Score and Comments

### eco Auto Inspection Dashboard

 Overall Score

Interior		8/10
Wheels		8/10
Exterior		4/10
Hood		7/10

### Overall ECO Comments

Vehicle is in Average Condition

Interior	Good Condition
Wheels	60% Worn
Exterior	Average Condition
Hood	Severely Damaged Condition



## All Images

DASHBOARD



FRONT SEATS VIEW



REAR SEATS VIEW



CLUSTER METER / INSTRUMENT PANEL



FRONT LEFT TYRE



FRONT RIGHT TYRE



REAR LEFT TYRE



REAR RIGHT TYRE



SPARE TYRES



FRONT VIEW



REAR VIEW



LEFT SIDE VIEW



RIGHT SIDE VIEW



LEFT FRONT CORNER VIEW



LEFT REAR CORNER VIEW



## All Images

RIGHT FRONT CORNER VIEW



RIGHT REAR CORNER VIEW



ENGINE COMPARTMENT



UNDERBODY




## Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.





[www.droom.in/eco](http://www.droom.in/eco)