

INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification



- a service by **droom**

ECO INSPECTION REPORT

Basic

Order ID : 201425

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Ajay

Inspection Date :
2022-06-24

Valid Till :
2022-09-24

7/10

Overall Score

- ✓ Evaluated across 6 segments
- ✓ 2 Owners , 6 Years Vehicle Age
- ✓ Accidental History

Inspected By



Tarunpal Singh

- ✓ Verified Technician
- 392+ vehicle inspected
- 2+ years experience

Honda Activa125 125cc Std, 2016



VEHICLE INFORMATION

MAKE	HONDA	REGISTRATION NO.	45AFH67
MODEL	ACTIVA125	VIN/CHASSIS NUMBER	234617
YEAR	2016	ODOMETER READING	13951
TRIM	125CC STD	INSURANCE EXPIRY	2022-1-09
COLOR	BLACK	MANUFACTURE DATE	09/2016
FUEL TYPE	PETROL	VEHICLE PASSING	PRIVATE
ENGINE CC	124	ENGINE NUMBER	452390
LOCATION	DELHI	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NA	SERVICE LOGS AVAILABLE	NA
TYRE LIFE REMAINING (KM)	12,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NA
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NA

ECO SCORE & OPTIONAL SPEND ESTIMATE

ECO SCORE

Tire	<div><div></div></div>	6 10
Control	<div><div></div></div>	8 10
Light	<div><div></div></div>	4 10
Oil	<div><div></div></div>	8 10
Chassis	<div><div></div></div>	8 10
Stand	<div><div></div></div>	8 10
Wheel	<div><div></div></div>	5 10

ECO COMMENTS

Tire	Average Condition
Control	Controls Are In Good Condition
Light	Lights Are Partially Working
Oil	Good Condition
Chassis	Chassis Frame Is In Good Condition
Stand	Stands Are In Good Condition
Wheel	

DESCRIPTION

miner scratches front left side indicator not workingoverall good condition

Ordered by: Ajay | Inspected date: 2022-06-24

Order Id: 201425

Overall Score



7/10



IMAGES (16)



Ordered by: Ajay | Inspected date: 2022-06-24

Order Id: 201425

Overall Score



7/10




DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE



www.droom.in/eco