

INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification



Independent




Unbiased



Objective



Comprehensive



Scientific

- a service by **droom**

ECO INSPECTION REPORT

India's Most Comprehensive And Scientific Vehicle Inspection Service

Ordered By




Anant Goel

10 / 02 / 2022

Gurgaon

Inspected By




Mitesh Karwa

Verified Technician

36+ Vehicle Inspected

4+ Years Experience

Triumph Bonneville T100 2020



₹7,64,860

Automobile from individual in good condition is valued

Vehicle Information


Make	Triumph	Registration Type	Private
Model	Bonneville T100	Registration No.	45AFH67
Year	2020	VIN/Chassis Number	234617
Trim	Ambiente 1.5L TDCI	Engine No.	452390
Color	Red	Manufacturing Date	2022-05-20
Fuel Type	Petrol	Registration Date	2022-07-15
Odometer Reading	2059	Insurance Expiry	2022-07-31
Engine CC	200	Location	Gurgaon
Number of Owners	2	Engine Sound Link	Listen Engine Sound

Key Highlights

Flood Damage	No	Permit Valid	Yes
Tyre Life Remaining (KM)	2,500	Insurance Copy Available	No
Dent	No	Service Logs Available	Full Service Log
Major Accidents	1	Bank Hypothecation	Yes
RC Copy Available	Duplicate	Bank NOC	NA
PUC Certificate Valid	Yes		

ECO Repair Estimate

Total Repair Estimate ₹ 18100



VEHICLE BODY

Vehicle Body View and Condition

N/A
NA

0
Critical

2
Bad

4
Below Average

6
Average

8
Good

10
Excellent

Fuel Tank

10

Front Cowl

8

Front Mudguard

8

Base Frame

10

Leg Guard

6

6 LH Cowl

10 LH Rear Foot Rest

6 LH Front Foot Rest

10 Side Stand

Rear Seat Condition

10

Rear Cowl

6

Rear Mudguard

10

Muffler/Silencer

10

Silencer Cover

4

10 Front Seat Condition

10 RH Cowl

6 RH Rear Foot Rest

10 RH Front Foot Rest




8 Center/Main Stand



Additional Checkpoints

Seat Covers are available and in good condition?	✗	Body is Rust Free?	✗
Side storage is available?	✓	Fuel lid is available and lock is working?	✓
Front License plate is available?	✓	Rear License Plate is available?	✓
License Plates are HSRP Compliant?	✓	Back rest is available?	N/A
Rear Reflector Condition is Good?	✓	Engraved VIN is matching with the document?	✓
Windscreen is available and working properly?	✓		

Vehicle Body Images



HANDLEBAR & CONTROL

Handlebar & Controls View and Condition

Legend for scores:

- N/A: NA
- 0: Critical
- 2: Bad
- 4: Below Average
- 6: Average
- 8: Good
- 10: Excellent


Inspection points and scores:

- LH Rear View Mirror: 8
- Clutch Lever: 8
- LH Handle Grip: 10
- Gear Shift Pedal: 4
- RH Rear View Mirror: 10
- Front Brake Lever: 10
- RH Handle Grip: 6
- Foot Brake Pedal: 10

Additional Checkpoints

Odometer is working properly?	✓	Speedometer is working properly?	✓
Tachometer is working properly?	✗	Fuel level indicator is working properly?	N/A
Handle Lock is working properly?	✓	Handle bar is working properly?	✓
Kick start lever is working properly?	N/A		

Handlebar & Control Images



LIGHTINGS AND SWITCHES

Lightings & Switches View and Condition

N/A	0	2	4	6	8	10
NA	Critical	Bad	Below Average	Average	Good	Excellent

Horn 6



Tail Light 4

Head light 4

Additional Checkpoints

Head Light High & Low Beam is working properly? ✓	Brake light is working properly? ✓
LH Front indicator is available and working? ✗	RH Front indicator is available and working? N/A
LH Rear Indicator is available and working? ✓	RH Rear Indicator is available and working? ✓
Light Switches are working properly? ✓	Ignition Switch is working properly? ✓
Daytime running light (DRL) is working properly? N/A	Fog Lamp is working properly? ✓
Self start is available and working properly? ✓	Fuel Choke is working properly? ✓

Lightings & Switches Images



WHEELS

Wheels View and Condition





Legend:

- N/A: NA
- 0: Critical
- 2: Bad
- 4: Below Average
- 6: Average
- 8: Good
- 10: Excellent

Component Conditions:


- Front Tire - Tubeless (MRF 90/100-17J): 6
- Front Wheel (Steel / Spokes): 10
- Front Brake: 4
- Rear Tire - Tubed (MRF 90/100-17J): 6
- Rear Wheel (Alloy): 4
- Rear Brake: 4

Wheel Images



TEST DRIVE AND PERFORMANCE

Mechanical Parts & Oils Performance View and Condition



Additional Checkpoints

Engine Noise is normal?	✓	Coolant Tank is Leakage Free?	N/A
Cable housing is in good condition?	✗	Engine Oil Tank is Leakage Free?	✗
Chain Tension is normal?	✓	Fuel Tank is Leakage Free?	✗
Chain is Lubricated properly?	✓	Exhaust Gas is normal?	✓
Brake Oil Tank is Leakage Free?	N/A	Malfunction Indicator Light is normal?	✓
Gear Oil Tank is Leakage Free?	✓		



Mechanical Parts & Performance Images

BATTERY



ENGINE



FRONT SUSPENSION



REAR SUSPENSION




Documents

REGISTRATION CERTIFICATE




INSURANCE COPY



NEED ATTENTION


Vehicle Body

FRONT FENDER





Remarks: Front Fender Damage
Repair Estimate: ₹ 400

REAR FENDER



Remarks: Rear Fender Cracked
Repair Estimate: ₹ 300


SILENCER/MUFFLER



Remarks: Silencer Not Working Properly
Repair Estimate: ₹ 350


Handlebar & Controls

LH REAR VIEW MIRROR



Remarks: Glass Broken
Repair Estimate: ₹ 150

RH REAR VIEW MIRROR





Remarks: Casing Torn
Repair Estimate: ₹ 100



NEED ATTENTION


Lightings & Switches

LH FRONT INDICATOR



Remarks: Bulb Needs To Be Replace
Repair Estimate: ₹ 300


KICK START LEVER



Remarks: Lever Bearing Needs To Be Replaced
Repair Estimate: ₹ 350


Wheels

FRONT BRAKE



Remarks: Front Brake Needs Grease
Repair Estimate: ₹ 50


BRAKES CONDITION REAR



Remarks: Rear Brake Need Overhaul
Repair Estimate: ₹ 800


Oils

ENGINE OIL LEVEL



Remarks: Engine Oil Needs Replacement
Repair Estimate: ₹ 400

CHAIN LUBRICATED



Remarks: Chain Performance Has Major Fault
Repair Estimate: ₹ 600



Other Images

BASE FRAME



SILENCER/MUFFLER



SILENCER COVER



FRONT FENDER/MUDGUARD



REAR FENDER/MUDGUARD



LEG GUARD



SIDE STAND



LEFT FRONT FOOT REST




RIGHT FRONT FOOT REST



LEFT REAR FOOT REST



RIGHT REAR FOOT REST



FRONT SEAT CONDITION



REAR SEAT CONDITION



REAR REFLECTOR



SIDE STORAGE



Other Images

LH REAR VIEW MIRROR



RH REAR VIEW MIRROR



GEAR SHIFT PEDAL




FRONT BRAKE LEVER



ODOMETER



SPEEDOMETER



TACHOMETER



FUEL LEVEL INDICATOR



WINDSCREEN



LH HANDLE GRIP



RH HANDLE GRIP



HANDLE LOCK



LH FRONT INDICATOR



RH FRONT INDICATOR



LH REAR INDICATOR



Other Images

RH REAR INDICATOR



DAYTIME RUNNING LIGHT (DRL)



SELF START SWITCH



FRONT BRAKE




REAR BRAKE



ENGINE OIL LEVEL



BRAKE OIL LEVEL



COOLANT LEVEL



CHAIN TENSION



SPROCKET CONDITION



Overall Comments

Bike is in good condition

Disclaimer


This inspection report was generated by ECO, a service arm of Droom Technology limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE





www.droom.in/eco