

INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification



Independent




Unbiased



Objective



Comprehensive



Scientific

- a service by **droom**

ECO INSPECTION REPORT

India's Most Comprehensive And Scientific Vehicle Inspection Service

Ordered By




Anant Goel

10 / 01 / 2021

Gurgaon

Inspected By




Mitesh Karwa

Verified Technician

36+ Vehicle Inspected

4+ Years Experience

Audi A4 Premium Plus, 2019



₹ 34,07,519

Automobile from individual in good condition is valued



Vehicle Information


Make	Audi	Transmission Type	Automatic
Model	A4	Registration Type	Private
Year	2019	Registration No.	DL10CG3657
Trim	Premium Plus	VIN/Chassis Number	16191
Exterior Color	Terra Gray	Kms Run	25105
Interior Color	Beige	Manufacturing Date	2022-05-20
Body Type	Sedan	Registration Date	2022-07-15
Fuel Type	Petrol	Insurance Expiry	2020-7-14
Engine CC	200	CNG Validity	2025-6-20
Engine No.	452390	Location	Janak Puri
Number of Owners	2	Engine Sound Link	Listen Engine Sound

Key Highlights

Flood Damage	No	Insurance Copy Available	No
Tyre Life Remaining (KM)	25,105	Service Logs Available	No
Dent	Yes	Bank Hypothecation	No
Major Accidents	No	Bank NOC	No
RC Copy Available	Yes (Original)		


ECO Repair Estimate

Total Repair Estimate ₹ 10250




ECO OVERALL SCORE BREAKDOWN


Interior




Exterior




Wheel



Hood



Test Drive



EXTERIOR

Vehicle Exterior View and Condition

0 Critical
 2 Bad
 4 Below Average
 6 Average
 8 Good
 10 Excellent

Grille 6		Paint Condition 10
Front Bumper 8		Hood 4
Front Windshield 8		Antenna 10
Left Fender 4		RH Fender 10
LH Side View Mirror 10		RH Side View Mirror 6
Roof 10		Pillars 10
LH Front Door 10		RH Front Door 8
LH Running Board 6		RH Running Board 6
LH Rear Door 10		RH Rear Door 4
Fuel Lid 2		RH Quarter Panel 8
LH Quarter Panel 6		Body Rust 8
Trunk Lid / Tail Gate 10		Rear Winshield 8
		Rear Bumper 10

Front License Plate is available?	✓
License Plates are HSRP complaint?	✗
Head Lights are working?	✓
Turn Signal lamps are working?	✗
Hazard Lamps are working?	✓
License plate light is working?	✓
Rear windshield wiper is working in good condition?	✓

Rear License Plate is available?	✓
HSRP colour sticker is available?	✗
Tail Lights are working?	✓
Fog Lamps are working?	N/A
Break lights are working?	✓
Front windshield wiper is working in good condition?	✓
Reverse parking lights are working?	✓



Exterior Images

FRONT VIEW



REAR VIEW



LEFT SIDE VIEW



RIGHT SIDE VIEW



LEFT FRONT CORNER VIEW



LEFT REAR CORNER VIEW



RIGHT FRONT CORNER VIEW



RIGHT REAR CORNER VIEW



INTERIOR

Vehicle Interior View and Condition



Reverse Parking Camera	6	Ceiling	8
Reverse Parking Sensors	10	Dashboard & Instrument Panel	8
Door Hinges	0	Odometer	10
Front LH Door Panel	8	Front RH Door Panel	8
Air Conditioning System	8	Heating System	6
Rear LH Door Panel	4	Pedals	8
		Rear RH Door Panel	4

Music System is working properly?	✓
Navigation System is working properly?	✗
Horn is loud & clear?	✓
Sun Visors are working properly?	✗
Luggage Compartment light is working properly?	N/A
Power Windows are working?	✓
Carpets are in good condition?	✓
Front Seat Belts are working properly?	N/A
Boot Lever is working properly?	✗
Front De-Fogger is available?	✓
USB port is available?	✓
Rear view mirror is functional?	✓
Passenger side seat adjustments are working properly?	✓
Odometer/Trip switches are working properly?	✓

Speakers are working properly?	✓
Steering Mounted Controls are working properly?	N/A
Handbrake is working properly?	✓
All Cabin lights are working properly?	N/A
Central Lock is working?	✓
Floor Mats are available?	✓
Seat Covers are in good condition?	✓
Rear Seat Belts are working properly?	N/A
Fuel Lid Lever is working properly?	✓
Bonnet Lever is working properly?	✗
Rear De-Fogger is available?	✓
Glove box light is working?	✓
Driver side seat adjustments are working properly?	✓



Interior Images

DASHBOARD VIEW



CLUSTER METER VIEW



FRONT SEATS



REAR SEATS



GLOVE BOX



INTERIOR REAR VIEW



INTERIOR FRONT VIEW




INTERIOR DOOR PANEL



WHEELS

Wheel View and Condition



Wheels Images

RIGHT FRONT TYRE



Remarks Tyre Tread Depth 6.3mm

Condition Good

RIGHT REAR TYRE



Remarks Tyre Tread Depth 6.2mm

Condition Good

LEFT FRONT TYRE



Remarks Tyre Tread Depth 3.5mm

Condition Bad

LEFT REAR TYRE




Remarks Tyre Tread Depth 6.3mm

Condition Good




TEST DRIVE

Test Drive and Condition





HOOD

Vehicle Hood View and Condition



Hood Images




Miscellaneous

Airbags are Available?	✓	Cruise Control is Available?	✓
VIN/Chassis Number matching with document?	✗	Medical Kit available?	✗
Vehicle jack and wrench available?	✓	MIL/Engine Light is OFF?	✓


Paint Condition

Hood	✓	Roof	✓
Left Fender	✗	Right Fender	✓
Left Front Door	✗	Left Rear Door	✓
Right Front Door	✗	Right Rear Door	✓
LH Running Board	✓	RH Running Board	✓
LH Quarter Panel	✓	RH Quarter Panel	✓
Trunk Lid / Tail Gate	✗	Pillars	✓

Images




Documents



NEED ATTENTION


Interior

CENTRAL LOCK



Remarks: Central Lock Not Working
Repair Estimate: ₹ 600


POWER WINDOW



Remarks: Power Window Not Working
Repair Estimate: ₹ 600

Wheel

LEFT FRONT TYRE



Remarks: Left front tyre is not in a good condition
Repair Estimate: ₹ 600


SPARE TYRE



Remarks: Spare tyre is not in a good condition
Repair Estimate: ₹ 600


Exterior

FOG LAMPS



Remarks: Major cracks in Fog Lamps
Repair Estimate: ₹ 900

LEFT FRONT DOOR



Remarks: Scratches/Dents in Front Door
Repair Estimate: ₹ 900



Other Images

GRILLE



FRONT BUMPER



REAR BUMPER



BONNET HOOD



FRONT WINDSHIELD



REAR WINDSHIELD



LEFT SIDE MIRROR



RIGHT SIDE MIRROR



LH FRONT DOOR



RIGHT FRONT DOOR



LEFT REAR DOOR



RIGHT REAR DOOR



LEFT FENDER



RIGHT FENDER



LEFT QUARTER PANEL



Other Images


RIGHT QUARTER PANEL



BOOT TRUNK LID



ROOF



FRONT LICENSE PLATE



REAR LICENSE PLATE



HSRP COLOUR STICKER



FRONT WINDSHIELD WIPER



REAR WINDSHIELD WIPER



ODOMETER



POWER WINDOWS



REAR VIEW MIRROR



ENGINE COMPARTMENT




UNDERCARRIAGE




BATTERY



TRUNK LID



Other Images



Overall Comments

Car is in average condition

Disclaimer


This inspection report was generated by ECO, a service arm of Droom Technology limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE





www.droom.in/eco