

INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification



Independent




Unbiased



Objective



Comprehensive



Scientific

- a service by **droom**

ECO INSPECTION REPORT

95+ Checkpoints Doorstep Inspection Service

Ordered By




Anant Goel

10 / 01 / 2022

Gurgaon

Inspected By




Mitesh Karwa

Verified Technician

36+ Vehicle Inspected

4+ Years Experience

Honda Activa 6G, 2021



Overall Score

#100 in Honda Activa 6G, 2021
#200 in Honda Activa
#800 in Scooters



₹ 64,860



Automobile from individual in good condition is valued

Vehicle Information


Make	Honda	Registration Type	Private
Model	Activa 6G	Registration No.	45AFH67
Year	2021	VIN/Chassis Number	234617
Trim	Standard	Engine No.	452390
Color	Blue	Manufacturing Date	2022-05-20
Fuel Type	Petrol	Registration Date	2022-07-15
Odometer Reading	2059	Insurance Expiry	2022-07-31
Engine CC	125	Location	Gurgaon
Number of Owners	1	Engine Sound Link	Listen Engine Sound

Key Highlights

Flood Damage	No	Permit Valid	Yes
Tyre Life Remaining (KM)	2,500	Insurance Copy Available	No
Dent	No	Service Logs Available	Full Service Log
Major Accidents	1	Bank Hypothecation	Yes
RC Copy Available	Duplicate	Bank NOC	NA
PUC Certificate Valid	Yes		

ECO Repair Estimate

Total Repair Estimate ₹ 7085



VEHICLE BODY

Vehicle Body View and Condition

N/A
NA

0
Critical

2
Bad

4
Below Average

6
Average

8
Good

10
Excellent

Head Light Cover

2

Front Panel (Apron)

10

Front Vender/
Mud Guard

6

Foot Board

8

Left Running
Board

2



10 Seat

6 Rear Left
Side Panel

6 Left Side
Footrest

8 Engine Cover

10 Centre Frame

Tail Light Cover

4

Rear Mudguard

10

Silencer/Muffler

8

Centre/Main Stand

8



10 Rear RH
Side Panel

6 Right Side
Footrest

10 Right Running
Board

8 Side Stand



VEHICLE BODY

Additional Checkpoints

Front License Plate is in Good Condition?



Rear License Plate is in Good Condition?



Body is Rust Free?



License Plates are HSRP Compliant?



Fuel Lid and Lock is Working in Good Condition?



Rear Reflector is in Good Condition?



Vehicle Body Images

FRONT VIEW



REAR VIEW



LEFT SIDE VIEW



RIGHT SIDE VIEW



HANDLEBAR & CONTROL



Handlebar & Controls View and Condition

Component	Condition Score
RH Rear View Mirror	6
RH Handle Grip	4
Front Brake Lever	10
LH Rear View Mirror	8
LH Handle Grip	4
Rear Brake Lever	8

Additional Checkpoints

Cluster Display is in Good Condition?	<input checked="" type="checkbox"/>	Handle Lock is Working in Good Condition?	<input checked="" type="checkbox"/>
Odometer is Working Properly?	<input type="checkbox"/>	Handle Bar is Working in Good Condition?	<input checked="" type="checkbox"/>
Speedometer is Working Properly?	<input checked="" type="checkbox"/>	Kick Start Pedal is Working in Good Condition?	<input checked="" type="checkbox"/>
Fuel Level Indicator is Working Properly?	<input checked="" type="checkbox"/>	RPM Meter is Working Properly?	<input checked="" type="checkbox"/>

Handlebar & Control Images



LIGHTINGS AND SWITCHES

Lightings & Switches View and Condition



Additional Checkpoints

Self Starter is Working Properly?	✓	Ignition Switch is Working in Good Condition?	✓
Light Switches are Working Properly?	✗	Front LH Indicator is Working in Good Condition?	✓
Front RH Indicator is Working in Good Condition?	✓	Rear LH Indicator is Working in Good Condition?	✓
Rear RH Indicator is Working in Good Condition?	✓	Brake Light is Working in Good Condition?	✓
Battery is Working in Good Condition?	✓		



TEST DRIVE AND PERFORMANCE

Mechanical Parts & Oils Performance View and Condition

Performance Legend:

- N/A: NA
- 0: Critical
- 2: Bad
- 4: Below Average
- 6: Average
- 8: Good
- 10: Excellent

Performance Callouts:

- Steering Performance: 10
- Acceleration Performance: 8
- Front Suspension: 4
- Brake Performance: 8
- Rear Suspension: 8
- Engine Performance: 8

Additional Checkpoints

Brake Fluid Bottle is Leakage Free?	N/A	Engine Sound is Normal?	✓
Engine Oil Tank is Leakage Free?	✗	Fuel Tank is Leakage Free?	✗
Exhaust Gas is Normal?	✓	Malfunction Indicator Light is Normal?	✗



WHEELS

Wheels View and Condition

N/A
NA

0
Critical

2
Bad

4
Below Average

6
Average

8
Good

10
Excellent

Front Tyre

2

Front Rim

8



6

Rear Tyre

8

Rear Rim

Wheel Images

FRONT WHEEL VIEW



REAR WHEEL VIEW



Documents

REGISTRATION CERTIFICATE



INSURANCE COPY

Insured Motor Vehicle Details & Premium Calculation		Type of Body		CC	Coverage	IDV in Rs.	Engine No.	Seating Ca
Registration Mark #	Year of Manuf.	Make of Vehicle	Model	Pin Code	Package	120861.00	380222	5
KA41N2842	2010	MARUTI ALTO LXI		560077				
Registration Authority		Trailer	Non Electrical Access.	Exec./Elect. Acc.	BI-Fuel Kit	Total Value	Net Premium Rs.	
120861.00		0.00	0.00	0.00	0.00	120861.00	1229.92	
A. Own Damage Premium(Rs.)				B. Third Party Premium(Rs.)				
Basic Premium	3507.87	Basic Premium	-					
Electrical Accessories (MT 24)	0.00	BI Fuel Kit (MT 25)	-					
BI Fuel Kit (MT 25)	0.00		-					
Add:		Add:	-					
Rattles (MT 31)	0.00	Legal Liability to Driver (MT 28)	-					
Foreign Vehicle Loading (MT 19)	0.00	Legal Liability to Employer (MT 29)	-					
Geographical Area Extension (MT 1)	0.00	PA to Passenger (MT 15)	-					
Trailers (MT 30)	0.00	Rattles (MT 31)	-					
		PA Owner Driver: CSI Rs 200000	-					
		Geographical Area Extension (MT 1)	-					
		MT 15	-					
Additional Loading		Less:						
Voluntary Excess Less 0% (MT 22A)	-0.00	Third Party Property Damage (MT 20)	-					
Anti Theft Device (MT 16)	-89.28	Limit of Liability Under Section II (ii) 750000	-					
Automobile Association (MT 8)	0.00		-					
Handicap Discount (MT 12)	0.00		-					
Vehicle Use (MT 13)	0.00		-					
No Claim Discount	(-35%)	-1939.30	-					
Any Other Loading Discount	(-35%)	-678.75	-					
Net (A)	1260.54	Net (B)	-					
Co-Insurance Details	Agent No./Share	Total Premium (A + B)	Rs. 2					
Co-Insurer 1	No Co-Insurer	Add Service Tax (402.99)+Swachh Bharat Cess(14.39)	-					
Co-Insurer 2	No Co-Insurer	Premium Paid Rs.	Rs. 2					




NEED ATTENTION

Vehicle Body

HEAD LIGHT COVER



Headlight Cover




Remarks

Major dents/scratches


Repair Estimate

₹ 650

LEFT RUNNING BOARD



Left Running Board



Remarks

Major dents/scratches


Repair Estimate

₹ 600

TAIL LIGHT COVER



Taillight Cover



Remarks


Minor dents/scratches

Repair Estimate

₹ 175

Handlebar & Controls

LH HANDLE GRIP




Remarks

Slippery Grip

Repair Estimate

₹ 80

RH HANDLE GRIP



Remarks

Slippery Grip

Repair Estimate


₹ 80



NEED ATTENTION


Lightings & Switches

HEAD LIGHT



Remarks: Broken/cracked
Repair Estimate: ₹ 2000


TAIL LIGHT



Remarks: Broken/cracked
Repair Estimate: ₹ 1800

Performance


FRONT SUSPENSION



Remarks: Fluid leakage/seepage
Repair Estimate: ₹ 500

Wheels

FRONT TYRE



Remarks: No air pressure
Repair Estimate: ₹ 1200



Other Images

HEAD LIGHT COVER



FRONT PANEL (APRON)



FRONT FENDER/ MUDGUARD



FOOT BOARD



LEFT RUNNING BOARD



CENTRE FRAME



REAR LH SIDE PANEL



ENGINE COVER



LEFT SIDE FOOT REST



SIDE STAND



CENTRE/ MAIN STAND



SEAT CONDITION




TAIL LIGHT COVER



REAR MUDGUARD



SILENCER/ MUFFLER



Other Images

REAR RH SIDE PANEL



RIGHT RUNNING BOARD



RIGHT SIDE FOOT REST



LH REAR VIEW MIRROR



RH REAR VIEW MIRROR



FRONT BRAKE LEVER



REAR BRAKE LEVER



HANDLE BAR



CLUSTER BAR



HEAD LIGHT



TAIL LIGHT



FRONT LH INDICATOR



FRONT RH INDICATOR



REAR LH INDICATOR



REAR RH INDICATOR



Other Images

BRAKE LIGHT



FRONT SUSPENSION



REAR SUSPENSION



INDICATOR LIGHT



FRONT TYRE CONDITION



REAR TYRE CONDITION



FRONT WHEEL RIM



REAR WHEEL RIM



Overall Comments

Scooter is in good condition

Disclaimer


This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE





www.droom.in/eco