INDIA'S MOST TRUSTWORTHY **AUTO INSPECTION & VERIFICATION SERVICE**



AI & Tech Driven Inspection & Certification

































Order ID: 20588 Generated: 12 Feb 2022

ECO INSPECTION REPORT

95+ Checkpoints Doorstep Inspection Service









Vehicle Information

Make	Honda	Registration Type	Private
Model	Activa 6G	Registration No.	45AFH67
Year	2021	VIN/Chassis Number	234617
Trim	Standard	Engine No.	452390
Color	Blue	Manufacturing Date	2022-05-20
Fuel Type	Petrol	Registration Date	2022-07-15
Odometer Reading	2059	Insurance Expiry	2022-07-31
Engine CC	125	Location	Gurgaon
Number of Owners	1	Engine Sound Link	Listen Engine Sound

Key Highlights



ECO Repair Estimate























Generated: 12 Feb 2022

VEHICLE BODY

Vehicle Body View and Condition






















Generated: 12 Feb 2022

VEHICLE BODY

Additional Checkpoints



Vehicle Body Images































Generated: 12 Feb 2022

HANDLEBAR & CONTROL

Handlebar & Controls View and Condition



Additional Checkpoints



Handlebar & Control Images


























Order ID: 20588 Generated: 12 Feb 2022

LIGHTINGS AND SWITCHES

Lightings & Switches View and Condition



Additional Checkpoints
























Order ID: 20588 Generated: 12 Feb 2022

TEST DRIVE AND PERFORMANCE

Mechanical Parts & Oils Performance View and Condition



Additional Checkpoints
























Generated: 12 Feb 2022

Order ID : 20588

WHEELS

Wheels View and Condition




Wheel Images





Documents



























Generated: 12 Feb 2022


Order ID : 20588

NEED ATTENTION


Vehicle Body








Handlebar & Controls



























Generated: 12 Feb 2022


NEED ATTENTION

Lightings & Switches






Performance



Wheels






















Generated: 12 Feb 2022

Other Images





















































Generated: 12 Feb 2022


Other Images






















































Generated: 12 Feb 2022


Other Images



































Generated: 12 Feb 2022

Overall Comments

Scooter is in good condition

Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.









