

ECO INSPECTION REPORT

Premium

Order ID : 20426

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Amit Pandey	Inspection Date : 2018-07-30	Valid Till : 2018-10-30
-----------------------------	---------------------------------	----------------------------

7/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 99 does not need attention
- ✓ 2 Owners , 4 Years Vehicle Age
- ✓ No Accidental History

Inspected By

 **Verified Technician**










271+ vehicle inspected
1+ years experience

Santosh Kumar

Volkswagen Vento Highline Diesel, 2014



VEHICLE INFORMATION			
MAKE	VOLKSWAGEN	TRANSMISSION TYPE	MANUAL
MODEL	VENTO	REGISTRATION NO.	UP16AW8469
YEAR	2014	VIN/CHASIS NUMBER	093800
TRIM	HIGHLINE DIESEL	KMS RUN	44584
COLOR	SILVER	INSURANCE EXPIRY	2018-11-12
BODY TYPE	SEDAN	LOCATION	GURUGRAM
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL











KEY HIGHLIGHTS			
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO
 TYRE LIFE REMAINING (KM)	18,000	 RC COPY AVAILABLE	YES (ORIGINAL)
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)
		 SERVICE LOGS AVAILABLE	NO
		 BANK HYPOTHECATION	NO
		 BANK NOC	NO

 Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

5,65,241

 Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE		TOTAL ESTIMATE SPEND 7,500	
 Interior	 7/10	Interior	0
 Wheel	 7/10	Wheel	0
 Test Drive	 7/10	Test Drive	7,000
 Exterior	 6/10	Exterior	500
 Hood	 7/10	Hood	0

Ordered by: Amit Pandey | Inspected date: 2018-07-30

Order Id: 20426

Overall Score



7/10



5,65,241



INTERIOR




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0
NAVIGATION	0	NO	0



IMAGES



Ordered by: Amit Pandey | Inspected date: 2018-07-30

Order Id: 20426

Overall Score **7/10**



5,65,241

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	6	TUARBO SOUND	7000
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
REAR PARKING SENSORS	7	GOOD	0
CRUISE CONTROL	0	NO	0
REAR VIEW CAMERA	0	NO	0

IMAGES




WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE	0
SPARE TYRE	9	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0
ENGINE OIL	5	AVERAGE	0
COOLANT LEVEL	5	AVERAGE	0

 IMAGES



Ordered by: Amit Pandey | Inspected date: 2018-07-30

Order Id: 20426

Overall Score  **7/10**



5,65,241

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	6	PAINT CANDITION GOOD	0
FRONT BUMPER	5	PAINTED	0
HOOD	5	PAINTED	0
SIDE VIEW MIRRORS	5	PAINTED	0
LH FENDER	5	PAINTED	0
LH FRONT DOOR	5	PAINTED	0
LH REAR DOOR	5	PAINTED	0
LH RUNNING BOARD	5	PAINTED	0
LH QUARTER PANEL	5	PAINTED	0
FUEL LID	5	PAINTED	0
REAR BUMPER	5	PAINTED	0
TAIL LIGHT	3	LEFT SIDE NOT WORKING	500
TRUNK LID/TAIL GATE	5	PAINTED	0

Ordered by: Amit Pandey | Inspected date: 2018-07-30

Order Id: 20426

Overall Score **7/10**



5,65,241

EXTERIOR (CONTINUED)

6/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH QUARTER PANEL	5	PAINTED	0
RH RUNNING BOARD	5	PAINTED	0
RH REAR DOOR	5	PAINTED	0
RH FRONT DOOR	5	PAINTED	0
RH FENDER	5	PAINTED	0

IMAGES





NEED ATTENTION ⚠️





DOCUMENTS



DESCRIPTION

car better candition car is painted but paint bettar candition tuarb sound

Ordered by: Amit Pandey | Inspected date: 2018-07-30

Order Id: 20426

Overall Score






7/10



5,65,241

IMAGES





Ordered by: Amit Pandey | Inspected date: 2018-07-30

Order Id: 20426

Overall Score



7/10



5,65,241

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.