

ECO INSPECTION REPORT Premium

Order ID : 20764

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : Manoj | Inspection Date : 2018-07-30 | Valid Till : 2018-10-30

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 98 does not need attention
- ✓ 1 Owner , 9 Years Vehicle Age
- ✓ No Accidental History

Inspected By












✓ Verified Technician
 272+ vehicle inspected
 1+ years experience

Santosh Kumar

Tata Manza Aura Safire Bs-Iv, 2009



VEHICLE INFORMATION			
MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	MANZA	REGISTRATION NO.	HR26BA7410
YEAR	2009	VIN/CHASIS NUMBER	01291
TRIM	AURA SAFIRE BS-IV	KMS RUN	73056
COLOR	SILVER	INSURANCE EXPIRY	2018-12-8
BODY TYPE	SEDAN	LOCATION	GURUGRAM
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	8,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO

 Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.






With this evaluation, the Fair Market Price for this vehicle comes to be:

1,68,643

 Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior		5 / 10
Wheel		5 / 10
Test Drive		6 / 10
Exterior		6 / 10
Hood		6 / 10

TOTAL ESTIMATE SPEND 46,300

Interior	11,000
Wheel	15,000
Test Drive	3,000
Exterior	15,000
Hood	2,300

Ordered by: Manoj | Inspected date: 2018-07-30

Order Id: 20764

Overall Score **6/10**





1,68,643

INTERIOR

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD	0
PEDALS	6	GOOD	0
CUP HOLDERS	6	GOOD	0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0
DOOR HINGES	4	LEFT FRANT DOOD BAD	500
SEAT & SEAT BELT	3	SEAT CAVAR BAD	2500
CENTRAL LOCK	0	NO	0
A/C VENTS & HEATER	3	CAMPRECER BAD	8000
NAVIGATION	0	NO	0

IMAGES



Ordered by: Manoj | Inspected date: 2018-07-30

Order Id: 20764

Overall Score **6/10**



1,68,643

TEST DRIVE

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
ENGINE NOISE	5	BAIRING SOUNDS	3000
SUSPENSION PERFORMANCE	5	MINOR SOUND	0
CRUISE CONTROL	0	NO	0
REAR PARKING SENSORS	0	NO	0
REAR VIEW CAMERA	0	NO	0

IMAGES




WHEEL

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE	6	AVERAGE	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0
TYRES	3	BAD	15000

 IMAGES



 NEED ATTENTION 




 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD	0
EXHAUST SYSTEM	6	GOOD	0
ENGINE OIL	3	BAD	1800
COOLANT LEVEL	4	BAD	500

 IMAGES



Ordered by: Manoj | Inspected date: 2018-07-30

Order Id: 20764

Overall Score



6/10



1,68,643

 EXTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
LH FRONT DOOR	6	GOOD	0
LH QUARTER PANEL	6	MINOR DENT	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH RUNNING BOARD	6	PAINTED	0
RH FRONT DOOR	6	GOOD	0
BODY RUST	6	GOOD	0
ROOF (REGULAR)	6	GOOD	0
PAINT CONDITION	6	GOOD	0
FRONT BUMPER	3	SCRATCH	2500
FOG LAMPS	0	NO	0
SIDE VIEW MIRRORS	5	PAINTED	0
LH FENDER	5	DENT	500
LH REAR DOOR	5	DENT	1000

Ordered by: Manoj | Inspected date: 2018-07-30

Order Id: 20764

Overall Score



6/10



1,68,643

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH RUNNING BOARD	5	PAINTED	0
REAR BUMPER	5	SCRATCH	2500
RH QUARTER PANEL	4	MAJOR SCRATCH	3000
RH REAR DOOR	4	MAJOR SCRATCH	3000
RH FENDER	4	DENT	2500

IMAGES



NEED ATTENTION ⚠️



Ordered by: Manoj | Inspected date: 2018-07-30

Order Id: 20764

Overall Score





6/10



1,68,643



DOCUMENTS



DESCRIPTION

car is bad condition tyers bad engine bairing sounds

Ordered by: Manoj | Inspected date: 2018-07-30

Order Id: 20764

Overall Score



6/10



1,68,643

IMAGES



Ordered by: Manoj | Inspected date: 2018-07-30

Order Id: 20764

Overall Score



6/10



1,68,643

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.