


ECO INSPECTION REPORT Premium

Order ID : 21140

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sonu Sharma	Inspection Date : 2018-08-02	Valid Till : 2018-11-02	 Inspected By  Lokesh Kumar ✓ Verified Technician 9+ vehicle inspected 1+ years experience
-----------------------------	---------------------------------	----------------------------	--

7/10





Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 115 does not need attention
- ✓ 2 Owners , 5 Years Vehicle Age
- ✓ No Accidental History

Audi A4 2.0 Tdi Premium Plus, 2013



VEHICLE INFORMATION			
MAKE	AUDI	TRANSMISSION TYPE	AUTOMATIC
MODEL	A4	REGISTRATION NO.	DL1CQ4443
YEAR	2013	VIN/CHASIS NUMBER	703840
TRIM	2.0 TDI PREMIUM PLUS	KMS RUN	78532
COLOR	RED	INSURANCE EXPIRY	2018-12-28
BODY TYPE	SEDAN	LOCATION	DELHI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	20,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

17,77,479



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE			TOTAL ESTIMATE SPEND 0				
 Interior	<div style="width: 70%;"></div>	7 / 10	0	0	0	0	0
 Wheel	<div style="width: 60%;"></div>	6 / 10	0	0	0	0	0
 Test Drive	<div style="width: 70%;"></div>	7 / 10	0	0	0	0	0
 Exterior	<div style="width: 60%;"></div>	6 / 10	0	0	0	0	0
 Hood	<div style="width: 60%;"></div>	6 / 10	0	0	0	0	0

Ordered by: sonu sharma | Inspected date: 2018-08-02

Order Id: 21140

Overall Score **7/10**





17,77,479

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	YESS	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION	6	YESS	0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0

IMAGES



Ordered by: sonu sharma | Inspected date: 2018-08-02

Order Id: 21140

Overall Score **7/10**





17,77,479

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
REAR PARKING SENSORS	7	YESS	0
CRUISE CONTROL	0	NO	0
REAR VIEW CAMERA	0	NO	0

IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	AVERAGE	0
SPARE TYRE	6	AVERAGE	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES



 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	7	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	AVERAGE	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	6	AVERAGE	0
COOLANT LEVEL	6	AVERAGE	0
BRAKE & COOLANT HOSE PIPES	6	AVERAGE	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: sonu sharma | Inspected date: 2018-08-02

Order Id: 21140

Overall Score  **7/10**



17,77,479

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	6	FULL PAINTED	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
FOG LAMPS	6	NO	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	FULL PAINTED	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	6	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	6	MINOR PAINTED	0
RH REAR DOOR	6	FULL. PAINTED	0
RH FRONT DOOR	7	GOOD	0
BODY RUST	6	NO	0
ROOF (SUN ROOF)	7	GOOD	0

Ordered by: sonu sharma | Inspected date: 2018-08-02

Order Id: 21140

Overall Score **7/10**




17,77,479

EXTERIOR (CONTINUED)


6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
PAINT CONDITION	6	GOOD.	0
LH RUNNING BOARD	5	MINOR PAINT	0
REAR BUMPER	5	FULL. PAINTED	0
RH RUNNING BOARD	5	PAINTED	0
RH FENDER	5	FULL PAINTED	0

IMAGES



NEED ATTENTION ⚠️



Ordered by: sonu sharma | Inspected date: 2018-08-02

Order Id: 21140

Overall Score




7/10



17,77,479



DOCUMENTS



DESCRIPTION

1 car condition good 2 both bumper , both fender , running board painted

Ordered by: sonu sharma | Inspected date: 2018-08-02

Order Id: 21140

Overall Score




7/10



17,77,479

IMAGES



Ordered by: sonu sharma | Inspected date: 2018-08-02

Order Id: 21140

Overall Score



7/10



17,77,479

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.