


ECO INSPECTION CERTIFICATE

Premium

Order ID : 48019

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Raman Kumar	Inspection Date : 2019-03-09	Valid Till : 2019-06-09	Inspected By  Pankaj Panwar
-----------------------------	---------------------------------	----------------------------	--

7/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **120** does not need attention
- ✔ **1** Owner , **8** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

127+ vehicle inspected
1+ years experience





Mitsubishi Pajero SFX 2.8, 2011



VEHICLE INFORMATION

MAKE	MITSUBISHI	TRANSMISSION TYPE	MANUAL
MODEL	PAJERO	REGISTRATION NO.	HR26BP7700
YEAR	2011	VIN/CHASIS NUMBER	007941
TRIM	SFX 2.8	KMS RUN	79848
COLOR	WHITE	INSURANCE EXPIRY	2019-3-9
BODY TYPE	COMPACT SUV	LOCATION	18 SEC
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	YES (PARTIAL)
 TYRE LIFE REMAINING (KM)	30,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	YES
 DENT	YES	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

7,93,601




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10
 Wheel	<div style="width: 70%; background-color: green;"></div>	7 / 10
 Test Drive	<div style="width: 80%; background-color: green;"></div>	8 / 10
 Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10
 Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10

TOTAL ESTIMATE SPEND 500



Ordered by: Raman Kumar | Inspected date: 2019-03-09

Order Id: 48019

Overall Score



7/10



7,93,601



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION AND WORKING PROPERLY	0
DOOR HINGES	7	GOOD CONDITION AND WORKING PROPERLY	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD CONDITION AND WORKING PROPERLY	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD CONDITION AND WORKING PROPERLY	0
HORN	7	GOOD CONDITION AND WORKING PROPERLY	0
SPEAKERS & MUSIC SYSTEM	7	GOOD CONDITION AND WORKING PROPERLY	0
HANDBRAKE	7	GOOD CONDITION AND WORKING PROPERLY	0
PEDALS	7	GOOD CONDITION AND WORKING PROPERLY	0
CENTRAL LOCK	7	GOOD CONDITION AND WORKING PROPERLY	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD CONDITION AND WORKING PROPERLY	0
POWER WINDOWS (YES - FRONT ONLY)	7	GOOD CONDITION AND WORKING PROPERLY	0
HAZARD LIGHT	7	GOOD	0
STEERING-MOUNTED CONTROLS	0	NOT AVAILABLE	0



IMAGES



Ordered by: Raman Kumar | Inspected date: 2019-03-09

Order Id: 48019

Overall Score



7/10



7,93,601


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION PERFORMANCE	7	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION FRONT SHOCKS	7	GOOD CONDITION AND WORKING PROPERLY	0
SUSPENSION REAR SHOCKS	7	GOOD CONDITION AND WORKING PROPERLY	0
TRANSMISSION ENGAGE	7	GOOD CONDITION AND WORKING PROPERLY	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

 IMAGES

 WHEEL

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD CONDITION AND WORKING PROPERLY	0
SPARE TYRE (YES)	7	GOOD CONDITION AND WORKING PROPERLY	0
WHEEL ASSEMBLY (STEEL RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD CONDITION AND WORKING PROPERLY	0
BRAKE FLUID LEVEL	7	MAXIMUM	0
ENGINE OIL	7	MAXIMUM	0
COOLANT LEVEL	7	MAXIMUM	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Raman Kumar | Inspected date: 2019-03-09

Order Id: 48019

Overall Score  **7/10**



7,93,601

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD CONDITION AND WORKING PROPERLY	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD CONDITION AND WORKING PROPERLY	0
FOG LAMPS	7	GOOD CONDITION AND WORKING PROPERLY	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD CONDITION AND WORKING PROPERLY	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD CONDITION AND WORKING PROPERLY	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD CONDITION AND WORKING PROPERLY	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	7	GOOD	0
TAIL LIGHT	7	GOOD CONDITION AND WORKING PROPERLY	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION AND WORKING PROPERLY	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0

RH QUARTER PANEL	6	MINORS SCRATCHES	500
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0

Ordered by: Raman Kumar | Inspected date: 2019-03-09

Order Id: 48019

Overall Score **7/10**



7,93,601



EXTERIOR (CONTINUED)

7/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD	0
RH FENDER	7	GOOD	0
BODY RUST	6		0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0

IMAGES





DOCUMENTS



DESCRIPTION

minor scratches minor dent

Ordered by: Raman Kumar | Inspected date: 2019-03-09

Order Id: 48019

Overall Score







7/10



7,93,601

 IMAGES





Ordered by: Raman Kumar | Inspected date: 2019-03-09

Order Id: 48019

Overall Score



7/10



7,93,601

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.