

ECO INSPECTION CERTIFICATE

Premium

Order ID : 62419

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
ANKIT JAIN

Inspection Date :
2019-04-15

Location :
KARNATAKA

6/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 117 does not need attention
- ✓ 1 Owner , 8 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Ajay Dalvi

- ✓ Verified Technician
- 44+ vehicle inspected
- 1+ years experience

Fiat Linea Dynamic 1.4, 2011



VEHICLE INFORMATION

MAKE	FIAT	ENGINE NUMBER	7080341
MODEL	LINEA	REGISTRATION NO.	KA53P8868
MFG. DATE	2011-04-30	VIN/CHASSIS NUMBER	24254BMZ
TRIM	DYNAMIC 1.4	ODOMETER READING	27849
COLOR	WINE	INSURANCE EXPIRY	2019-4-29
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	30,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,53,589




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

TOTAL ESTIMATE SPEND 4,500



Ordered by: ANKIT JAIN | Inspected date: 2019-04-15

Order Id: 62419

Overall Score



6/10



2,53,589



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
HAZARD LIGHT	7	GOOD	0
POWER WINDOWS (YES - FRONT ONLY)	2	MOT OK	1000



IMAGES



Ordered by: ANKIT JAIN | Inspected date: 2019-04-15

Order Id: 62419

Overall Score **6/10**




2,53,589

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES




WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (STEEL RIM)	6	GOOD	0

 IMAGES




 HOOD




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	7		0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES





Ordered by: ANKIT JAIN | Inspected date: 2019-04-15

Order Id: 62419

Overall Score  **6/10**



2,53,589

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
FRONT BUMPER	6	GOOD	0
HEAD LIGHTS	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	6	GOOD	0
LH FRONT DOOR	6	GOOD	0
LH REAR DOOR	6	GOOD	0
LH RUNNING BOARD	6	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	6	GOOD	0
REAR BUMPER	6	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH RUNNING BOARD	6	GOOD	0
RH REAR DOOR	6	GOOD	0
RH FRONT DOOR	7	GOOD	0
BODY RUST	7	GOOD	0

Ordered by: ANKIT JAIN | Inspected date: 2019-04-15

Order Id: 62419

Overall Score **6/10**



2,53,589






EXTERIOR (CONTINUED)

6/10



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
ROOF (REGULAR)	6	GOOD	0
PAINT CONDITION	7	GOOD	0
FOG LAMPS	3	NOT OK	500
RH QUARTER PANEL	3	NOT OK	1500
RH FENDER	3	MEJOR SCTACHES	1500

IMAGES






NEED ATTENTION



DOCUMENTS



DESCRIPTION

normal scraches. door glass not working

Ordered by: ANKIT JAIN | Inspected date: 2019-04-15

Order Id: 62419

Overall Score
























6/10



2,53,589

IMAGES





Ordered by: ANKIT JAIN | Inspected date: 2019-04-15

Order Id: 62419

Overall Score



6/10



2,53,589

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.