


ECO INSPECTION CERTIFICATE

Premium

Order ID : 75112

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Vikas Madan	Inspection Date : 2019-05-20	Location : SEC 45	Inspected By  Manoj Kumar
-----------------------------	---------------------------------	----------------------	--

8/10


Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **1** Year Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

686+ vehicle inspected
1+ years experience

Volkswagen Vento HIGHLINE PETROL AT, 2018



VEHICLE INFORMATION			
MAKE	VOLKSWAGEN	ENGINE NUMBER	02200
MODEL	VENTO	REGISTRATION NO.	HR26DM9052
MFG. DATE	01/2018	VIN/CHASSIS NUMBER	113412
TRIM	HIGHLINE PETROL AT	ODOMETER READING	9996
COLOR	BLUE	INSURANCE EXPIRY	2019-5-20
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	35,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	YES	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



orangebookvalue.com

Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

10,20,997




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #0070C0, #ccc);"></div>	8 / 10
Wheel	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #0070C0, #ccc);"></div>	8 / 10
Test Drive	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #0070C0, #ccc);"></div>	8 / 10
Exterior	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #0070C0, #ccc);"></div>	8 / 10
Hood	<div style="width: 80%; height: 10px; background: linear-gradient(to right, #0070C0, #ccc);"></div>	8 / 10

TOTAL ESTIMATE SPEND 1,500



Ordered by: vikas Madan | Inspected date: 2019-05-20

Order Id: 75112

Overall Score



8/10



10,20,997



INTERIOR




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8		0
DOOR HINGES	8		0
CARPET & FLOOR MAT	8		0
SEAT & SEAT BELT	8		0
DASHBOARD & INSTRUMENT PANEL	8		0
HORN	9		0
SPEAKERS & MUSIC SYSTEM	8		0
HANDBRAKE	9		0
STEERING-MOUNTED CONTROLS	8		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	8		0
CUP HOLDERS	8		0
NAVIGATION (NO)	10		0
ODOMETER	9		0
POWER WINDOWS (YES)	8		0
HAZARD LIGHT	8		0



IMAGES



Ordered by: vikas Madan | Inspected date: 2019-05-20

Order Id: 75112

Overall Score **8/10**



10,20,997

TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	8		0
ENGINE NOISE	8		0
IGNITION SYSTEM	8		0
SUSPENSION PERFORMANCE	8		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	9		0
TRANSMISSION ENGAGE	8		0
CRUISE CONTROL (YES)	8		0
REAR PARKING SENSORS (YES)	9		0
REAR VIEW CAMERA (YES)	9		0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8		0
RH APRON	8		0
RADIATOR	8		0
WIRING	8		0
BATTERY	9		0
BRAKE FLUID LEVEL	8		0
ENGINE OIL	8		0
COOLANT LEVEL	8		0
BRAKE & COOLANT HOSE PIPES	8		0
UNDERCARRIAGE	8		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: vikas Madan | Inspected date: 2019-05-20

Order Id: 75112

Overall Score  **8/10**



10,20,997

 **EXTERIOR**

 **8/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	8		0
HEAD LIGHTS	8		0
GRILLE	8		0
TURN SIGNAL	8		0
FOG LAMPS	8		0
HOOD	8		0
PILLAR	8		0
FRONT WINDSHIELD	8		0
SIDE VIEW MIRRORS	8		0
LH FENDER	8		0
LH FRONT DOOR	8		0
LH REAR DOOR	8		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	8		0
REAR BUMPER	8		0
TAIL LIGHT	8		0
TRUNK LID/TAIL GATE	6	MINOR PAINT REMOVE	500
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	6	MINOR SCRATCHES	500
RH RUNNING BOARD	8		0
RH REAR DOOR	6	MINOR SCRATCHES	500

Ordered by: vikas Madan | Inspected date: 2019-05-20

Order Id: 75112

Overall Score **8/10**



10,20,997

EXTERIOR (CONTINUED)

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0

IMAGES





DOCUMENTS



DESCRIPTION

minor scratches and minor dent

Ordered by: vikas Madan | Inspected date: 2019-05-20

Order Id: 75112

Overall Score



8/10



10,20,997

IMAGES





Ordered by: vikas Madan | Inspected date: 2019-05-20

Order Id: 75112

Overall Score



8/10



10,20,997

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.