


# ECO INSPECTION CERTIFICATE

Premium

Order ID : 75041

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Aman Gajwani	Inspection Date : 2019-05-22	Location : GHAZIABAD	Inspected By   Verified Technician 304+ vehicle inspected 1+ years experience Kishan Kumar
------------------------------	---------------------------------	-------------------------	---

**6/10**

**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 115 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

## Toyota Etios Liva GD, 2013



### VEHICLE INFORMATION

MAKE	TOYOTA	ENGINE NUMBER	43738
MODEL	ETIOS LIVA	REGISTRATION NO.	UP14BY7859
MFG. DATE	04/2013	VIN/CHASSIS NUMBER	43738
TRIM	GD	ODOMETER READING	64440
COLOR	SILVER	INSURANCE EXPIRY	2019-5-22
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLENO		BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**3,27,692**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 70%;"></div>	7 / 10
Test Drive	<div style="width: 50%;"></div>	5 / 10
Exterior	<div style="width: 70%;"></div>	7 / 10
Hood	<div style="width: 70%;"></div>	7 / 10

#### TOTAL ESTIMATE SPEND 150



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75041

Overall Score



6/10



3,27,692



## INTERIOR



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
ODOMETER	7		0
POWER WINDOWS (YES)	6	AVERAGE CONDITION	0
HAZARD LIGHT	7		0
STEERING-MOUNTED CONTROLS	0	NA	0
NAVIGATION (YES)	0	NA	0



## IMAGES



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75041

Overall Score



6/10



3,27,692



## TEST DRIVE




5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	6	AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	AVERAGE CONDITION	0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	0	NA	0
REAR PARKING SENSORS (YES)	0	NA	0
REAR VIEW CAMERA (YES)	0	NA	0



## IMAGES




## WHEEL



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	6	AVERAGE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	7		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

 IMAGES



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75041

Overall Score  **6/10**



**3,27,692**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7		0
FRONT BUMPER	7		0
HEAD LIGHTS	7		0
GRILLE	7		0
TURN SIGNAL	7		0
HOOD	7		0
PILLAR	7		0
FRONT WINDSHIELD	6	AVERAGE CONDITION	0
SIDE VIEW MIRRORS	7		0
LH FENDER	6	SCRATCHES	150
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	7		0
LH QUARTER PANEL	7		0
FUEL LID	7		0
REAR WINDSHIELD	6	AVERAGE CONDITION	0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0
RH FRONT DOOR	7		0



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75041

Overall Score  **6/10**




**3,27,692**

**EXTERIOR (CONTINUED)**


**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7		0
BODY RUST	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
FOG LAMPS	0	NA	0


**IMAGES**



 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

all body painted and scratches



Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75041

Overall Score




6/10



3,27,692

IMAGES







Ordered by: Aman Gajwani | Inspected date: 2019-05-22

Order Id: 75041

Overall Score



6/10



3,27,692

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.