

# ECO INSPECTION CERTIFICATE

Premium

Order ID : 76343


121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


**Ordered By :**  
 SHRI GAIKWAD SHAMRAO  
 NAMDEO


**Inspection Date :**  
 2019-05-24

**Location :**  
 PUNE

**7/10**  
  
**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 2 Years Vehicle Age
- ✓ No Accidental History

 **Inspected By**


✓ **Verified Technician**  
 115+ vehicle inspected  
 1+ years experience

Prasad Kulkarni






## Honda Brio Vx Mt, 2017



### VEHICLE INFORMATION

<b>MAKE</b>	HONDA	<b>ENGINE NUMBER</b>	
<b>MODEL</b>	BRIO	<b>REGISTRATION NO.</b>	MH12PC8709
<b>MFG. DATE</b>	01/2017	<b>VIN/CHASSIS NUMBER</b>	MAKDD175AHN400558
<b>TRIM</b>	VX MT	<b>ODOMETER READING</b>	5024
<b>COLOR</b>	SILVER	<b>INSURANCE EXPIRY</b>	2019-4-8
<b>BODY TYPE</b>	HATCHBACK	<b>VEHICLE PASSING</b>	PRIVATE
<b>FUEL TYPE</b>	PETROL	<b>ENGINE SOUND LINK</b>	NIL

### KEY HIGHLIGHTS

 <b>FLOOD DAMAGE</b>	NO	 <b>MAJOR ACCIDENT(S)</b>	NO	 <b>SERVICE LOGS AVAILABLE</b>	NO
 <b>TYRE LIFE REMAINING (KM)</b>	10,000	 <b>RC COPY AVAILABLE</b>	ORIGINAL	 <b>BANK HYPOTHECATION</b>	NO
 <b>DENT</b>	NO	 <b>INSURANCE COPY AVAILABLE</b>	NO	 <b>BANK NOC</b>	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**5,03,333**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 <b>Interior</b>		<b>7 / 10</b>
 <b>Wheel</b>		<b>7 / 10</b>
 <b>Test Drive</b>		<b>8 / 10</b>
 <b>Exterior</b>		<b>7 / 10</b>
 <b>Hood</b>		<b>7 / 10</b>

#### TOTAL ESTIMATE SPEND 0



Ordered by: SHRI GAIKWAD SHAMRAO NAMDEO | Inspected date: 2019-05-24

Order Id: 76343

Overall Score



7/10



5,03,333



## INTERIOR





7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD CONDITION	0
DOOR HINGES	7	GOOD HINGES	0
CARPET & FLOOR MAT	7	GOOD CONDITION	0
SEAT & SEAT BELT	7	WORKING	0
DASHBOARD & INSTRUMENT PANEL	7	WORKING	0
HORN	7	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	7	WORKING	0
HANDBRAKE	7	GOOD HOLD	0
STEERING-MOUNTED CONTROLS	7	WORKING	0
PEDALS	7	GOOD CONDITION	0
CENTRAL LOCK	7	WORKING	0
A/C VENTS & HEATER	7	GOOD COOLING	0
CUP HOLDERS	7	GOOD CONDITION	0
NAVIGATION (NO)	10		0
ODOMETER	7	WORKING	0
POWER WINDOWS (YES)	7	WORKING	0
HAZARD LIGHT	7	WORKING	0



## IMAGES






## TEST DRIVE

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	GOOD PERFORMANCE	0
BRAKE PERFORMANCE	7	GOOD BRAKES	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	NORMAL OPERATING NOISE	0
IGNITION SYSTEM	7	WORKING	0
SUSPENSION PERFORMANCE	7	GOOD PERFORMANCE	0
SUSPENSION FRONT SHOCKS	7	GOOD PERFORMANCE	0
SUSPENSION REAR SHOCKS	7	MINIMUM SHOCKS	0
TRANSMISSION ENGAGE	7	SMOOTH GEAR SHIFTING	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



## IMAGES




## WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD TREAD	0
SPARE TYRE (YES)	7	GOOD TREAD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD CONDITION	0

 IMAGES



 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD PASTING	0
RH APRON	7	GOOD PASTING	0
RADIATOR	7	WORKING	0
WIRING	7	GOOD CONDITION	0
BATTERY	7	FULLY CHARGED	0
BRAKE FLUID LEVEL	7	MAXIMUM LEVEL	0
ENGINE OIL	7	GOOD OIL	0
COOLANT LEVEL	7	MAXIMUM LEVEL	0
BRAKE & COOLANT HOSE PIPES	7	GOOD CONDITION	0
UNDERCARRIAGE	7	GOOD CONDITION	0
EXHAUST SYSTEM	7	NO SMOKE	0

 IMAGES



Ordered by: SHRI GAIKWAD SHAMRAO NAMDEO | Inspected date: 2019-05-24

Order Id: 76343

Overall Score  **7/10**



**5,03,333**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD CONDITION	0
FRONT BUMPER	7	GOOD CONDITION	0
HEAD LIGHTS	7	WORKING	0
GRILLE	7	GOOD CONDITION	0
TURN SIGNAL	7	WORKING	0
FOG LAMPS	7	WORKING	0
HOOD	7	GOOD CONDITION	0
PILLAR	7	GOOD CONDITION	0
FRONT WINDSHIELD	7	GOOD VISIBILITY	0
SIDE VIEW MIRRORS	7	GOOD CONDITION	0
LH FENDER	7	GOOD CONDITION	0
LH FRONT DOOR	7	GOOD CONDITION	0
LH REAR DOOR	7	GOOD CONDITION	0
LH RUNNING BOARD	7	GOOD CONDITION	0
LH QUARTER PANEL	7	GOOD CONDITION	0
FUEL LID	7	GOOD CONDITION	0
REAR WINDSHIELD	7	GOOD VISIBILITY	0
REAR BUMPER	7	GOOD CONDITION	0
TAIL LIGHT	7	GOOD CONDITION	0
TRUNK LID/TAIL GATE	7	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	7	SMALL SPACE	0
RH QUARTER PANEL	7	GOOD CONDITION	0
RH RUNNING BOARD	7	GOOD CONDITION	0
RH REAR DOOR	7	GOOD CONDITION	0



Ordered by: SHRI GAIKWAD SHAMRAO NAMDEO | Inspected date: 2019-05-24

Order Id: 76343

Overall Score  **7/10**




**5,03,333**

## EXTERIOR (CONTINUED)


**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	7	GOOD CONDITION	0
RH FENDER	7	GOOD CONDITION	0
BODY RUST	7	NO BODY RUST	0
ROOF (REGULAR)	7	GOOD CONDITION	0
PAINT CONDITION	7	GOOD CONDITION	0

## IMAGES



## DOCUMENTS



## DESCRIPTION

Good condition

[www.droom.in/eco](http://www.droom.in/eco)

[eco@droom.in](mailto:eco@droom.in)

Contact No. 18004070707 (Toll Free)

-a service by  **droom**.in



Ordered by: SHRI GAIKWAD SHAMRAO NAMDEO | Inspected date: 2019-05-24

Order Id: 76343

Overall Score




7/10



5,03,333

IMAGES





Ordered by: SHRI GAIKWAD SHAMRAO NAMDEO | Inspected date: 2019-05-24

Order Id: 76343

Overall Score



7/10



5,03,333

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.