

# ECO INSPECTION CERTIFICATE

Premium


Order ID : 76469

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Pramod Kumar	Inspection Date : 2019-05-27	Location : DELHI	Inspected By  <b>Verified Technician</b> 427+ vehicle inspected 1+ years experience Aabid Ali
<div style="text-align: center;"> <h2>7/10</h2> <p><b>Overall Score</b></p> </div> <ul style="list-style-type: none"> <li>✓ Evaluated across 5 segments</li> <li>✓ Covered 121+ checkpoints</li> <li>✓ 120 does not need attention</li> <li>✓ 1 Owner , 7 Years Vehicle Age</li> <li>✓ No Accidental History</li> </ul>			

## Hyundai Verna 1.6 CRDI SX, 2012



### VEHICLE INFORMATION

MAKE	HYUNDAI	ENGINE NUMBER	069210
MODEL	VERNA	REGISTRATION NO.	DL10CD3081
MFG. DATE	02/2012	VIN/CHASSIS NUMBER	052054
TRIM	1.6 CRDI SX	ODOMETER READING	54322
COLOR	SLEEK SILV	INSURANCE EXPIRY	2018-4-9
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	20,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	YES
DENT	NO	INSURANCE COPY AVAILABLENO		BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

**4,42,845**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

Interior		7 / 10
Wheel		7 / 10
Test Drive		7 / 10
Exterior		7 / 10
Hood		7 / 10

#### TOTAL ESTIMATE SPEND 600



Ordered by: Pramod kumar | Inspected date: 2019-05-27

Order Id: 76469

Overall Score  **7/10**




**4,42,845**

## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	7	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
HANDBRAKE	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
PEDALS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0

## IMAGES



Ordered by: Pramod kumar | Inspected date: 2019-05-27

Order Id: 76469

Overall Score  **7/10**



**4,42,845**

## TEST DRIVE

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7	SMOOTHLY ROTATE BOTH SIDE	0
BRAKE PERFORMANCE	7	GOOD	0
CLUTCH PERFORMANCE	7	GOOD	0
ENGINE NOISE	7	GOOD	0
IGNITION SYSTEM	7	GOOD	0
SUSPENSION PERFORMANCE	7	GOOD	0
SUSPENSION FRONT SHOCKS	7	GOOD	0
SUSPENSION REAR SHOCKS	7	GOOD	0
TRANSMISSION ENGAGE	7	GOOD	0
CRUISE CONTROL (YES)	7	GOOD	0
REAR PARKING SENSORS (YES)	7	GOOD	0
REAR VIEW CAMERA (NO)	10		0

## IMAGES




## WHEEL

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7	GOOD	0
SPARE TYRE (YES)	7	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	7	GOOD	0
WIRING	7	GOOD	0
BATTERY	7	GOOD	0
BRAKE FLUID LEVEL	7	GOOD	0
ENGINE OIL	7	GOOD	0
COOLANT LEVEL	7	GOOD	0
BRAKE & COOLANT HOSE PIPES	7	GOOD	0
UNDERCARRIAGE	7	GOOD	0
EXHAUST SYSTEM	7	GOOD	0

 IMAGES



Ordered by: Pramod kumar | Inspected date: 2019-05-27

Order Id: 76469

Overall Score  **7/10**



**4,42,845**

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	7	GOOD	0
HEAD LIGHTS	7	GOOD	0
GRILLE	7	GOOD	0
TURN SIGNAL	7	GOOD	0
HOOD	7	GOOD	0
PILLAR	7	GOOD	0
FRONT WINDSHIELD	7	GOOD	0
SIDE VIEW MIRRORS	7	GOOD	0
LH FENDER	7	GOOD	0
LH FRONT DOOR	7	GOOD	0
LH REAR DOOR	7	GOOD	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	7	GOOD	0
REAR BUMPER	7	GOOD	0
TAIL LIGHT	7	GOOD	0
TRUNK LID/TAIL GATE	7	GOOD	0
LUGGAGE COMPARTMENT LIGHT	7	GOOD	0
RH QUARTER PANEL	7	GOOD	0
RH RUNNING BOARD	7	GOOD	0
RH REAR DOOR	7	GOOD	0
RH FRONT DOOR	7	GOOD	0

Ordered by: Pramod kumar | Inspected date: 2019-05-27

Order Id: 76469

Overall Score  **7/10**




**4,42,845**








## EXTERIOR (CONTINUED)

**7/10**


INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	7	GOOD	0
BODY RUST	7	GOOD	0
ROOF (REGULAR)	7	GOOD	0
PAINT CONDITION	7	GOOD	0
FOG LAMPS	5	L.S NOT WORKING NEED TO CHANGE FOGLAMB	600

## IMAGES





 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

L. S foglamb not working need to change

Ordered by: Pramod kumar | Inspected date: 2019-05-27

Order Id: 76469

Overall Score




7/10


















4,42,845

 IMAGES







Ordered by: Pramod kumar | Inspected date: 2019-05-27

Order Id: 76469

Overall Score



7/10



4,42,845

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.