

ECO INSPECTION CERTIFICATE

Premium

Order ID : 49436

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.


Ordered By : ACHINT CHACHADA	Inspection Date : 2019-03-14	Valid Till : 2019-06-14
---------------------------------	---------------------------------	----------------------------

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 116 does not need attention
- ✓ 1 Owner , 9 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ **Verified Technician**

5+ vehicle inspected

1+ years experience

Shoab Khan







Fiat Linea ACTIVE 1.3, 2010



VEHICLE INFORMATION

MAKE	FIAT	TRANSMISSION TYPE	MANUAL
MODEL	LINEA	REGISTRATION NO.	MH31DC9220
YEAR	2010	VIN/CHASIS NUMBER	17634ENZ
TRIM	ACTIVE 1.3	KMS RUN	65009
COLOR	WHITE	INSURANCE EXPIRY	2018-11-17
BODY TYPE	SEDAN	LOCATION	NAGPUR
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	1,000	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

2,55,421




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 70%;"></div>	7 / 10
 Wheel	<div style="width: 70%;"></div>	7 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 11,300



Ordered by: ACHINT CHACHADA | Inspected date: 2019-03-14

Order Id: 49436

Overall Score



6/10



2,55,421



INTERIOR



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	6		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	6		0
SPEAKERS & MUSIC SYSTEM	6		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	7		0
CENTRAL LOCK	6		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	6		0
NAVIGATION (NO)	10		0
ODOMETER	6		0
POWER WINDOWS (YES)	6		0
HAZARD LIGHT	7		0



IMAGES



Ordered by: ACHINT CHACHADA | Inspected date: 2019-03-14

Order Id: 49436

Overall Score **6/10**




2,55,421

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	6		0
ENGINE NOISE	7		0
IGNITION SYSTEM	6		0
SUSPENSION PERFORMANCE	6		0
SUSPENSION FRONT SHOCKS	6		0
SUSPENSION REAR SHOCKS	6		0
TRANSMISSION ENGAGE	6		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0

IMAGES



WHEEL

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (ALLOY RIM)	7		0

 IMAGES

 HOOD

 6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6		0
RH APRON	6		0
RADIATOR	6		0
WIRING	6		0
BATTERY	7	ON WARRANTY	0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	6		0
COOLANT LEVEL	6		0
BRAKE & COOLANT HOSE PIPES	6		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	6		0

 IMAGES


Ordered by: ACHINT CHACHADA | Inspected date: 2019-03-14

Order Id: 49436

Overall Score  **6/10**



2,55,421

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6		0
FRONT BUMPER	6		0
HEAD LIGHTS	6		0
GRILLE	6		0
TURN SIGNAL	6		0
FOG LAMPS	6		0
HOOD	6		0
PILLAR	6		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	6		0
LH FRONT DOOR	6		0
LH RUNNING BOARD	6		0
FUEL LID	6		0
REAR WINDSHIELD	6		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	6		0
LUGGAGE COMPARTMENT LIGHT	6		0
RH QUARTER PANEL	6		0
RH RUNNING BOARD	6		0
RH REAR DOOR	6		0
RH FRONT DOOR	6		0
ROOF (REGULAR)	6		0
PAINT CONDITION	7		0

Ordered by: ACHINT CHACHADA | Inspected date: 2019-03-14

Order Id: 49436

Overall Score



6/10



2,55,421



EXTERIOR (CONTINUED)



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH REAR DOOR	5	MINOR SCRATCH AND DENT	2200
LH QUARTER PANEL	5	SCRATCH	2500
REAR BUMPER	5	MINOR SCRATCHES	2200
RH FENDER	5	MINOR DAMAGE	2200
BODY RUST	5	MINOR RUST	2200



IMAGES



NEED ATTENTION



Ordered by: ACHINT CHACHADA | Inspected date: 2019-03-14

Order Id: 49436

Overall Score





6/10



2,55,421



DOCUMENTS



DESCRIPTION

nice condition original paint and minor scratches

Ordered by: ACHINT CHACHADA | Inspected date: 2019-03-14

Order Id: 49436

Overall Score




6/10



2,55,421

IMAGES



Ordered by: ACHINT CHACHADA | Inspected date: 2019-03-14

Order Id: 49436

Overall Score



6/10



2,55,421

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.