

ECO INSPECTION CERTIFICATE

Premium

Order ID : 46538

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Vishal Goyal	Inspection Date : 2019-03-05	Valid Till : 2019-06-05	Inspected By  Ankush Dhadave
------------------------------	---------------------------------	----------------------------	---

6/10

Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **113** does not need attention
- ✔ **1** Owner , **8** Years Vehicle Age
- ✔ No Accidental History

✔ **Verified Technician**

21+ vehicle inspected
1+ years experience

Tata Safari 4X4 VX DICOR BS IV, 2011



VEHICLE INFORMATION

MAKE	TATA	TRANSMISSION TYPE	MANUAL
MODEL	SAFARI	REGISTRATION NO.	MH04ET 2877
YEAR	2011	VIN/CHASIS NUMBER	BNA00536
TRIM	4X4 VX DICOR BS IV	KMS RUN	52284
COLOR	WHITE	INSURANCE EXPIRY	2016-9-14
BODY TYPE	SEDAN	LOCATION	MUMBAI
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	1,500	RC COPY AVAILABLE	YES (ORIGINAL)	BANK HYPOTHECATION	NO
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

5,41,446




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 60%;"></div>	6 / 10
Wheel	<div style="width: 50%;"></div>	5 / 10
Test Drive	<div style="width: 70%;"></div>	7 / 10
Exterior	<div style="width: 60%;"></div>	6 / 10
Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 41,600



Ordered by: Vishal Goyal | Inspected date: 2019-03-05

Order Id: 46538

Overall Score



6/10



5,41,446



INTERIOR





6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD	0
DOOR HINGES	6	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	6	GOOD	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD	0
HORN	6	GOOD	0
SPEAKERS & MUSIC SYSTEM	6	GOOD	0
HANDBRAKE	6	GOOD	0
STEERING-MOUNTED CONTROLS	6	GOOD NO ANY NOISE	0
PEDALS	6	GOOD	0
CENTRAL LOCK	6	ALL DOOR WORKING GOOD	0
A/C VENTS & HEATER	6	GOOD	0
CUP HOLDERS	6	GOOD	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD	0
POWER WINDOWS (YES)	6	GOOD	0
HAZARD LIGHT	6	GOOD	0



IMAGES



Ordered by: Vishal Goyal | Inspected date: 2019-03-05

Order Id: 46538

Overall Score **6/10**



5,41,446

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	GOOD	0
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION PERFORMANCE	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	6	GOOD	0
ENGINE NOISE	4	BALT NOISE	2000

IMAGES









WHEEL

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
SPARE TYRE (YES)	6	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	6	RUSTY & SCRATCH	0
TYRES	3	ALL 4 TIRES CRACK & HARD NEED RPL	30000

 IMAGES



 NEED ATTENTION 





 HOOD



6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	GOOD	0
RH APRON	6	GOOD	0
RADIATOR	6	GOOD	0
WIRING	6	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
ENGINE OIL	6	GOOD	0
COOLANT LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	6	GOOD NO DAMAGE	0
EXHAUST SYSTEM	6	NO DAMAGE	0

 IMAGES



Ordered by: Vishal Goyal | Inspected date: 2019-03-05

Order Id: 46538

Overall Score  **6/10**



5,41,446

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	6	GOOD	0
HOOD	6	GOOD	0
PILLAR	6	GOOD	0
FRONT WINDSHIELD	6	GOOD	0
SIDE VIEW MIRRORS	6	GOOD	0
LH FENDER	6	GOOD	0
LH RUNNING BOARD	6	GOOD	0
LH QUARTER PANEL	6	GOOD	0
FUEL LID	6	GOOD	0
REAR WINDSHIELD	6	GOOD	0
REAR BUMPER	6	GOOD	0
TAIL LIGHT	6	GOOD	0
TRUNK LID/TAIL GATE	6	GOOD	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD	0
RH QUARTER PANEL	6	MINOR SCRATCH	0
RH RUNNING BOARD	6	MINOR SCRATCH	0
RH REAR DOOR	6	GOOD	0
RH FENDER	6	MINOR SCRATCH	0
BODY RUST	6	MINOR RUSTY	0
ROOF (REGULAR)	6	GOOD	0
PAINT CONDITION	6	GOOD	0
FRONT BUMPER	4	DAMAGE B/P WORK	2500

Ordered by: Vishal Goyal | Inspected date: 2019-03-05

Order Id: 46538

Overall Score **6/10**



5,41,446

EXTERIOR (CONTINUED)

6/10




INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
HEAD LIGHTS	5	RHS H/L RPL	2800
FOG LAMPS	4	NOT WORK NEED RPL	1000
LH FRONT DOOR	4	DAMAGE	1500
LH REAR DOOR	4	DAMAGE	1500
RH FRONT DOOR	5	MINOR SCRATCH	300

IMAGES





 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

body dent& paint work required ,rhs head light rpl,all 5 tires rpl.engine balt noise. no insurance .

Ordered by: Vishal Goyal | Inspected date: 2019-03-05

Order Id: 46538

Overall Score
















6/10



5,41,446

IMAGES





Ordered by: Vishal Goyal | Inspected date: 2019-03-05

Order Id: 46538

Overall Score



6/10



5,41,446

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.