


# ECO INSPECTION CERTIFICATE


Premium

Order ID : 82604

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Om Parkash Arora	Inspection Date : 2019-06-14	Location : DELHI	Inspected By   Abu Zafar
----------------------------------	---------------------------------	---------------------	--

**7/10**  
  
**Overall Score**

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 111 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History

✓ Verified Technician  
 490+ vehicle inspected  
 1+ years experience










## Maruti Suzuki Swift Dzire VDI, 2013



### VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	173972
MODEL	SWIFT DZIRE	REGISTRATION NO.	DL8CAD1323
MFG. DATE	09/2013	VIN/CHASSIS NUMBER	380058
TRIM	VDI	ODOMETER READING	65312
COLOR	GREY	INSURANCE EXPIRY	2017-6-14
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	<a href="#">LISTEN ENGINE SOUND</a>

### KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	15,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:











**3,98,648**




Very Good Condition

### ECO SCORE & REPAIR COST ESTIMATE

#### ECO SCORE

 Interior		7 / 10
 Wheel		7 / 10
 Test Drive		8 / 10
 Exterior		6 / 10
 Hood		7 / 10

#### TOTAL ESTIMATE SPEND 11,100



Ordered by: Om Parkash arora | Inspected date: 2019-06-14

Order Id: 82604

Overall Score  **7/10**







**3,98,648**


## INTERIOR

**7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
PEDALS	7		0
CENTRAL LOCK	7		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (NO)	10		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0
DOOR PANEL	5	NEED WASHING	300
STEERING-MOUNTED CONTROLS	0	NA	0

## IMAGES





NEED ATTENTION



TEST DRIVE



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	7		0
BRAKE PERFORMANCE	7		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	7		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (NO)	10		0



IMAGES



INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	7		0
WHEEL ASSEMBLY (STEEL RIM)	7		0





IMAGES



HOOD

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	7		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	7		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	7		0

IMAGES



Ordered by: Om Parkash arora | Inspected date: 2019-06-14

Order Id: 82604

Overall Score  **7/10**



**3,98,648**

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FRONT BUMPER	7		0
GRILLE	7		0
HOOD	6	MINOR DENT	1000
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	6	MINOR SCRATCHES	1000
LH FRONT DOOR	6	MINOR SCRATCHES	1000
LH REAR DOOR	6	MINOR SCRATCHES	1000
LH RUNNING BOARD	7		0
FUEL LID	7		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TRUNK LID/TAIL GATE	7		0
RH QUARTER PANEL	7		0
RH RUNNING BOARD	6	MINOR DENT AND SCRATCHES	1000
RH REAR DOOR	7		0
RH FRONT DOOR	7		0
RH FENDER	7		0
ROOF (REGULAR)	7		0
PAINT CONDITION	7		0
LICENSE PLATE	4	FRONT NEED REPLACE	300
HEAD LIGHTS	4	RHS NOT WORKING NEED REPAIR WIRING CONNECTION	500
TURN SIGNAL	2	RHS DAMAGE NEED REPLACE	300



Ordered by: Om Parkash arora | Inspected date: 2019-06-14

Order Id: 82604

Overall Score  **7/10**



**3,98,648**

## EXTERIOR (CONTINUED)


**6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
FOG LAMPS	2	BOTH SIDE NOT WORKING AND DAMAGE NEED REPLACE	1500
LH QUARTER PANEL	4	NEED REPAIR DENT AND SCRATCHES	2500
TAIL LIGHT	4	RHS DAMAGE NEED REPLACE	700
LUGGAGE COMPARTMENT LIGHT	0	NA	0
BODY RUST	0	NA	0

## IMAGES











 **NEED ATTENTION** 





## DOCUMENTS



## DESCRIPTION

tire change after the 15000km

Ordered by: Om Parkash arora | Inspected date: 2019-06-14

Order Id: 82604

Overall Score




7/10








3,98,648

IMAGES







Ordered by: Om Parkash arora | Inspected date: 2019-06-14

Order Id: 82604

Overall Score



7/10



3,98,648

## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.