

ECO INSPECTION CERTIFICATE

Premium

Order ID : 83055

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Atul Gupta

Inspection Date :
2019-07-26

Location :
THANE WEST

Inspected By

6/10



Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 120 does not need attention
- ✓ 1 Owner , 6 Years Vehicle Age
- ✓ No Accidental History



Gaurav Phodkar

- ✓ Verified Technician
- 304+ vehicle inspected
- 1+ years experience




Maruti Suzuki Swift Dzire ZDI, 2013



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	13A2085467
MODEL	SWIFT DZIRE	REGISTRATION NO.	MH04FZ9303
MFG. DATE	02/2013	VIN/CHASSIS NUMBER	MA3FJEB1S00278235
TRIM	ZDI	ODOMETER READING	77858
COLOR	WHITE	INSURANCE EXPIRY	2020-3-25
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	YES (COMPREHENSIVE)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,66,279




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 300



Ordered by: atul Gupta | Inspected date: 2019-07-26

Order Id: 83055

Overall Score



6/10



4,66,279



INTERIOR









6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD CONDITION	0
DOOR HINGES	6	ACCEPTABLE CONDITION	0
CARPET & FLOOR MAT	6	GOOD CONDITION	0
SEAT & SEAT BELT	6	GOOD WORKING	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD WORKING	0
HORN	6	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	GOOD WORKING	0
HANDBRAKE	6	WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	6	GOOD WORKING	0
PEDALS	6	WORKING GOOD	0
CENTRAL LOCK	6	GOOD WORKING	0
A/C VENTS & HEATER	6	GOOD COOLING	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	GOOD WORKING	0
POWER WINDOWS (YES)	6	GOOD WORKING	0
HAZARD LIGHT	6	WORKING GOOD	0



IMAGES






TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	WORKING SMOOTHLY	0
BRAKE PERFORMANCE	6	GOOD WORKING	0
CLUTCH PERFORMANCE	6	WORKING GOOD	0
ENGINE NOISE	6	NORMAL NOISE	0
IGNITION SYSTEM	6	PROPERLY WORKING	0
SUSPENSION PERFORMANCE	6	GOOD SUSPENSION	0
SUSPENSION FRONT SHOCKS	6	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	6	GOOD CONDITION	0
TRANSMISSION ENGAGE	6	SMOOTH GEAR ENGAGEMENT	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (NO)	10		0
REAR VIEW CAMERA (YES)	6	GOOD WORKING	0




IMAGES



WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	NORMAL WEAR AND TEAR	0
SPARE TYRE (YES)	6	GOOD CONDITION	0

 IMAGES

 HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	ACCEPTABLE CONDITION	0
RH APRON	6	ACCEPTABLE CONDITION	0
RADIATOR	6	GOOD WORKING	0
WIRING	6	ACCEPTABLE CONDITION	0
BATTERY	6	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	MAXIMUM LEVEL	0
ENGINE OIL	6	GOOD VISCOSITY	0
COOLANT LEVEL	6	MAXIMUM LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	ACCEPTABLE CONDITION	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	GOOD WORKING	0

 IMAGES




Ordered by: atul Gupta | Inspected date: 2019-07-26

Order Id: 83055

Overall Score  **6/10**



4,66,279

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD CONDITION	0
FRONT BUMPER	6	GOOD CONDITION	0
HEAD LIGHTS	6	GOOD WORKING	0
GRILLE	6	ACCEPTABLE CONDITION	0
TURN SIGNAL	6	GOOD WORKING	0
FOG LAMPS	6	ACCEPTABLE	0
HOOD	6	GOOD CONDITION	0
PILLAR	6	GOOD CONDITION	0
FRONT WINDSHIELD	6	CLEAR VISIBILITY	0
SIDE VIEW MIRRORS	6	GOOD CONDITION	0
LH FENDER	6	GOOD CONDITION	0
LH FRONT DOOR	6	GOOD CONDITION	0
LH REAR DOOR	6	GOOD CONDITION	0
LH RUNNING BOARD	6	GOOD CONDITION	0
LH QUARTER PANEL	6	GOOD CONDITION	0
FUEL LID	6	GOOD CONDITION	0
REAR WINDSHIELD	6	CLEAR VISIBILITY	0
REAR BUMPER	6	GOOD CONDITION	0
TRUNK LID/TAIL GATE	6	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD SPACE , LIGHT GOOD WORKING	0
RH QUARTER PANEL	6	GOOD CONDITION	0
RH RUNNING BOARD	6	GOOD CONDITION	0
RH REAR DOOR	6	GOOD CONDITION	0
RH FRONT DOOR	6	GOOD CONDITION	0

Ordered by: atul Gupta | Inspected date: 2019-07-26

Order Id: 83055

Overall Score



6/10



4,66,279



EXTERIOR (CONTINUED)




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FENDER	6	GOOD CONDITION	0
BODY RUST	6	NO RUST FOUND	0
ROOF (REGULAR)	6	GOOD CONDITION	0
PAINT CONDITION	6	GOOD CONDITION	0
TAIL LIGHT	5	NEED TO CHECK WIRING	300




IMAGES






 **NEED ATTENTION** 



 **DOCUMENTS**



 **DESCRIPTION**

Ordered by: atul Gupta | Inspected date: 2019-07-26

Order Id: 83055

Overall Score




6/10




4,66,279

IMAGES (70)







Ordered by: atul Gupta | Inspected date: 2019-07-26

Order Id: 83055

Overall Score



6/10



4,66,279

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.