

ECO INSPECTION CERTIFICATE

Premium

Order ID : 83053

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By :
Atul Gupta

Inspection Date :
2019-07-27

Location :
THANE WEST

6/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 4 Years Vehicle Age
- ✓ No Accidental History

Inspected By



Gaurav Phodkar

- ✓ Verified Technician
- 308+ vehicle inspected
- 1+ years experience










Volkswagen Cross Polo 1.2 MPI, 2015



VEHICLE INFORMATION

MAKE	VOLKSWAGEN	ENGINE NUMBER	89698
MODEL	CROSS POLO	REGISTRATION NO.	MH04GU9368
MFG. DATE	02/2015	VIN/CHASSIS NUMBER	MEXB15605FT071087
TRIM	1.2 MPI	ODOMETER READING	34297
COLOR	BLACK	INSURANCE EXPIRY	2019-6-2
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	25,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO (3RD PARTY)	 BANK NOC	NO








Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

4,52,601




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

 Interior	<div style="width: 60%;"></div>	6 / 10
 Wheel	<div style="width: 60%;"></div>	6 / 10
 Test Drive	<div style="width: 70%;"></div>	7 / 10
 Exterior	<div style="width: 60%;"></div>	6 / 10
 Hood	<div style="width: 60%;"></div>	6 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: atul Gupta | Inspected date: 2019-07-27

Order Id: 83053

Overall Score



6/10



4,52,601



INTERIOR








6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	GOOD CONDITION	0
DOOR HINGES	6	ACCEPTABLE CONDITION	0
CARPET & FLOOR MAT	6	GOOD CONDITION	0
SEAT & SEAT BELT	6	GOOD WORKING	0
DASHBOARD & INSTRUMENT PANEL	6	GOOD WORKING CONDITION	0
HORN	6	GOOD SOUND	0
SPEAKERS & MUSIC SYSTEM	6	GOOD WORKING	0
HANDBRAKE	6	WORKING PROPERLY	0
STEERING-MOUNTED CONTROLS	6	GOOD WORKING	0
PEDALS	6	GOOD WORKING	0
CENTRAL LOCK	6	WORKING GOOD	0
A/C VENTS & HEATER	6	GOOD COOLING	0
CUP HOLDERS	6	NO DAMAGE	0
NAVIGATION (NO)	10		0
ODOMETER	6	WORKING GOOD	0
POWER WINDOWS (YES)	6	GOOD WORKING	0
HAZARD LIGHT	6	GOOD WORKING	0



IMAGES





TEST DRIVE




7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	SMOOTHLY WORKING	0
BRAKE PERFORMANCE	6	GOOD WORKING	0
CLUTCH PERFORMANCE	6	GOOD WORKING	0
ENGINE NOISE	6	NORMAL NOISE	0
IGNITION SYSTEM	6	PROPERLY WORKING	0
SUSPENSION PERFORMANCE	6	GOOD SUSPENSION	0
SUSPENSION FRONT SHOCKS	6	GOOD CONDITION	0
SUSPENSION REAR SHOCKS	6	GOOD CONDITION	0
TRANSMISSION ENGAGE	6	SMOOTH GEAR ENGAGEMENT	0
CRUISE CONTROL (NO)	10		0
REAR PARKING SENSORS (YES)	6	GOOD WORKING	0
REAR VIEW CAMERA (NO)	10		0



IMAGES




WHEEL




6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	NORMAL WEAR AND TEAR	0
SPARE TYRE (YES)	6	GOOD CONDITION	0

 IMAGES

 HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	ACCEPTABLE CONDITION	0
RH APRON	6	ACCEPTABLE CONDITION	0
RADIATOR	6	GOOD WORKING	0
WIRING	6	ACCEPTABLE CONDITION	0
BATTERY	6	GOOD CONDITION	0
BRAKE FLUID LEVEL	6	MAXIMUM LEVEL	0
ENGINE OIL	6	GOOD VISCOSITY	0
COOLANT LEVEL	6	MAXIMUM LEVEL	0
BRAKE & COOLANT HOSE PIPES	6	ACCEPTABLE CONDITION	0
UNDERCARRIAGE	6	NO DAMAGE	0
EXHAUST SYSTEM	6	GOOD WORKING	0

 IMAGES




Ordered by: atul Gupta | Inspected date: 2019-07-27

Order Id: 83053

Overall Score  **6/10**



4,52,601

 **EXTERIOR**

 **6/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	GOOD CONDITION	0
FRONT BUMPER	6	GOOD CONDITION	0
HEAD LIGHTS	6	GOOD WORKING	0
GRILLE	6	ACCEPTABLE CONDITION	0
TURN SIGNAL	6	GOOD WORKING	0
FOG LAMPS	6	GOOD WORKING	0
HOOD	6	GOOD CONDITION	0
PILLAR	6	GOOD CONDITION	0
FRONT WINDSHIELD	6	CLEAR VISIBILITY	0
SIDE VIEW MIRRORS	6	GOOD CONDITION	0
LH FENDER	6	GOOD CONDITION	0
LH FRONT DOOR	6	GOOD CONDITION	0
LH REAR DOOR	6	GOOD CONDITION	0
LH RUNNING BOARD	6	GOOD CONDITION	0
LH QUARTER PANEL	6	GOOD CONDITION	0
FUEL LID	6	GOOD CONDITION	0
REAR WINDSHIELD	6	CLEAR VISIBILITY	0
REAR BUMPER	6	GOOD CONDITION	0
TAIL LIGHT	6	GOOD WORKING	0
TRUNK LID/TAIL GATE	6	GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	6	GOOD SPACE	0
RH QUARTER PANEL	6	GOOD CONDITION	0
RH RUNNING BOARD	6	GOOD CONDITION	0
RH REAR DOOR	6	GOOD CONDITION	0

Ordered by: atul Gupta | Inspected date: 2019-07-27

Order Id: 83053

Overall Score



6/10



4,52,601



EXTERIOR (CONTINUED)














6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	6	GOOD CONDITION	0
RH FENDER	6	GOOD CONDITION	0
BODY RUST	6	NO RUST FOUND	0
ROOF (REGULAR)	6	GOOD CONDITION	0
PAINT CONDITION	6	GOOD CONDITION	0








IMAGES





 DOCUMENTS



 DESCRIPTION

good condition car

Ordered by: atul Gupta | Inspected date: 2019-07-27

Order Id: 83053

Overall Score





6/10




4,52,601

IMAGES (68)







Ordered by: atul Gupta | Inspected date: 2019-07-27

Order Id: 83053

Overall Score



6/10



4,52,601

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.