


ECO INSPECTION CERTIFICATE

Premium

Order ID : 98896

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Manish J. Sejpal	Inspection Date : 2019-07-29	Location : AHMEDABAD	Inspected By  PANCHAL HITESH Verified Technician 3+ vehicle inspected 1+ years experience
----------------------------------	---------------------------------	-------------------------	--

7/10






Overall Score

- ✔ Evaluated across **5** segments
- ✔ Covered **121+** checkpoints
- ✔ **121** does not need attention
- ✔ **1** Owner , **1** Year Vehicle Age
- ✔ No Accidental History

Maruti Suzuki Ciaz ZXI+ RS, 2018



VEHICLE INFORMATION			
MAKE	MARUTI SUZUKI	ENGINE NUMBER	K14BN71737
MODEL	CIAZ	REGISTRATION NO.	GJ33B3602
MFG. DATE	07/2019	VIN/CHASSIS NUMBER	MA3EXMG1500300969
TRIM	ZXI+ RS	ODOMETER READING	23216
COLOR	WHITE	INSURANCE EXPIRY	2019-7-29
BODY TYPE	SEDAN	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS					
 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	5,00,000	 RC COPY AVAILABLE	ORIGINAL	 BANK HYPOTHECATION	NOT APPLICABLE
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO



orangebookvalue.com






Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine.
With this evaluation, the Fair Market Price for this vehicle comes to be:

8,33,975



Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE			TOTAL ESTIMATE SPEND 0				
 Interior	<div style="width: 70%; background-color: green;"></div>	7 / 10	0	0	0	0	0
 Wheel	<div style="width: 80%; background-color: green;"></div>	8 / 10					
 Test Drive	<div style="width: 70%; background-color: green;"></div>	7 / 10					
 Exterior	<div style="width: 70%; background-color: green;"></div>	7 / 10					
 Hood	<div style="width: 70%; background-color: green;"></div>	7 / 10					

Ordered by: Manish J. Sejpal | Inspected date: 2019-07-29

Order Id: 98896

Overall Score **7/10**




8,33,975

INTERIOR

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	7		0
DOOR HINGES	7		0
CARPET & FLOOR MAT	7		0
SEAT & SEAT BELT	7		0
DASHBOARD & INSTRUMENT PANEL	7		0
HORN	7		0
SPEAKERS & MUSIC SYSTEM	7		0
HANDBRAKE	7		0
STEERING-MOUNTED CONTROLS	7		0
PEDALS	8		0
CENTRAL LOCK	8		0
A/C VENTS & HEATER	7		0
CUP HOLDERS	7		0
NAVIGATION (YES)	7		0
ODOMETER	7		0
POWER WINDOWS (YES)	7		0
HAZARD LIGHT	7		0

IMAGES



Ordered by: Manish J. Sejpal | Inspected date: 2019-07-29

Order Id: 98896

Overall Score **7/10**



8,33,975

TEST DRIVE

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6		0
BRAKE PERFORMANCE	8		0
CLUTCH PERFORMANCE	7		0
ENGINE NOISE	7		0
IGNITION SYSTEM	7		0
SUSPENSION PERFORMANCE	7		0
SUSPENSION FRONT SHOCKS	8		0
SUSPENSION REAR SHOCKS	7		0
TRANSMISSION ENGAGE	7		0
CRUISE CONTROL (YES)	7		0
REAR PARKING SENSORS (YES)	7		0
REAR VIEW CAMERA (YES)	8		0

IMAGES



WHEEL

8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	7		0
SPARE TYRE (YES)	8		0
WHEEL ASSEMBLY (ALLOY RIM)	8		0

 IMAGES




 HOOD



7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	7		0
RH APRON	7		0
RADIATOR	7		0
WIRING	7		0
BATTERY	8		0
BRAKE FLUID LEVEL	7		0
ENGINE OIL	8		0
COOLANT LEVEL	7		0
BRAKE & COOLANT HOSE PIPES	7		0
UNDERCARRIAGE	7		0
EXHAUST SYSTEM	8		0

 IMAGES



Ordered by: Manish J. Sejpal | Inspected date: 2019-07-29

Order Id: 98896

Overall Score  **7/10**



8,33,975

 **EXTERIOR**

 **7/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8		0
FRONT BUMPER	6		0
HEAD LIGHTS	8		0
GRILLE	7		0
TURN SIGNAL	7		0
FOG LAMPS	7		0
HOOD	8		0
PILLAR	7		0
FRONT WINDSHIELD	7		0
SIDE VIEW MIRRORS	7		0
LH FENDER	7		0
LH FRONT DOOR	7		0
LH REAR DOOR	7		0
LH RUNNING BOARD	8		0
LH QUARTER PANEL	8		0
FUEL LID	8		0
REAR WINDSHIELD	7		0
REAR BUMPER	7		0
TAIL LIGHT	7		0
TRUNK LID/TAIL GATE	7		0
LUGGAGE COMPARTMENT LIGHT	8		0
RH QUARTER PANEL	8		0
RH RUNNING BOARD	7		0
RH REAR DOOR	7		0

Ordered by: Manish J. Sejal | Inspected date: 2019-07-29

Order Id: 98896

Overall Score **7/10**




8,33,975

EXTERIOR (CONTINUED)


7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8		0
RH FENDER	8		0
BODY RUST	8		0
ROOF (REGULAR)	8		0
PAINT CONDITION	8		0

IMAGES



DOCUMENTS



DESCRIPTION

good

Ordered by: Manish J. Sejpal | Inspected date: 2019-07-29

Order Id: 98896

Overall Score




7/10



8,33,975

IMAGES (17)



Ordered by: Manish J. Sejpal | Inspected date: 2019-07-29

Order Id: 98896

Overall Score



7/10



8,33,975

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.