


ECO INSPECTION CERTIFICATE

Premium

Order ID : 107745

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Jalaluddin Hashmi	Inspection Date : 2019-09-09	Location : PRABHADEVI	Inspected By  Verified Technician 413+ vehicle inspected 1+ years experience Shashank Mahadik
--	--	---------------------------------	--

5/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 104 does not need attention
- ✓ 2 Owners , 6 Years Vehicle Age
- ✓ No Accidental History

Maruti Suzuki Alto 800 LXI, 2013



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	072080
MODEL	ALTO 800	REGISTRATION NO.	MH04GE4299
MFG. DATE	07/2013	VIN/CHASSIS NUMBER	286413
TRIM	LXI	ODOMETER READING	42054
COLOR	GREY	INSURANCE EXPIRY	2019-8-19
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	PETROL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	8,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

1,38,403




ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 50%;"></div>	5 / 10
Wheel	<div style="width: 60%;"></div>	6 / 10
Test Drive	<div style="width: 50%;"></div>	5 / 10
Exterior	<div style="width: 50%;"></div>	5 / 10
Hood	<div style="width: 60%;"></div>	6 / 10
Electrical & Lighting	<div style="width: 50%;"></div>	5 / 10

TOTAL ESTIMATE SPEND 14,800



www.droom.in/eco

eco@droom.in

Contact No. 18004070707 (Toll Free)

-a service by .in

Ordered by: Jalaluddin Hashmi | Inspected date: 2019-09-09

Order Id: 107745

Overall Score



5/10



1,38,403



INTERIOR




5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	6	BOTH DOOR'S PANELS ARE IN AVERAGE CONDITION	0
DOOR HINGES	6	BOTH DOOR'S HINGES & LATCH ARE WORKING IN AVERAGE CONDITION	0
CARPET & FLOOR MAT	6	CARPET IS IN AVERAGE CONDITION	0
SEAT & SEAT BELT	6	SEATS/SEAT COVERS ARE IN AVERAGE CONDITION	0
DASHBOARD & INSTRUMENT PANEL	6	DASHBOARD/INSTRUMENT PANEL IS IN AVERAGE CONDITION	0
HORN	6	HORN SOUND IS IN AVERAGE CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	SPEAKER'S SOUND IS IN GOOD CONDITION	0
HANDBRAKE	6	HAND BRAKE IS IN AVERAGE CONDITION	0
PEDALS	6	ALL PEDAL'S BOOT IS IN AVERAGE CONDITION	0
CENTRAL LOCK	8	ALL DOOR'S LOCKS ARE WORKING IN GOOD CONDITION	0
A/C VENTS & HEATER	10	AC/HEATER IS WORKING AND COOLING/HEATING	0
ODOMETER	6	ODOMETER IS WORKING IN AVERAGE CONDITION	0
POWER WINDOWS (YES - FRONT ONLY)	6	ALL POWER WINDOWS ARE WORKING IN AVERAGE CONDITION.	0
HAZARD LIGHT	6	HAZARD LIGHT IS WORKING IN AVERAGE CONDITION	0
STEERING-MOUNTED CONTROLS	0	STEERING MOUNTED CONTROLS NOT WORKING	0
CUP HOLDERS	0	CUP HOLDERS DAMAGED	0

NAVIGATION (NO)

0

0

 IMAGES

 TEST DRIVE

5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	6	STEERING WORKING IS IN AVERAGE CONDITION	0
BRAKE PERFORMANCE	6	BRAKES ARE WORKING IN AVERAGE CONDITION	0
CLUTCH PERFORMANCE	6	CLUTCH IS WORKING IN AVERAGE CONDITION	0
ENGINE NOISE	6	SOMETIMES MINOR NOISE IN ENGINE.	0
IGNITION SYSTEM	6	IGNITION SYSTEM IS WORKING IN AVERAGE CONDITION.	0
SUSPENSION PERFORMANCE	6	SUSPENSION PERFORMANCE IS IN AVERAGE CONDITION	0
SUSPENSION FRONT SHOCKS	6	FRONT SUSPENSION IS WORKING IN AVERAGE CONDITION	0
SUSPENSION REAR SHOCKS	6	REAR SUSPENSION IS WORKING IN AVERAGE CONDITION	0
TRANSMISSION ENGAGE	6	TRANSMISSION IS WORKING IN AVERAGE CONDITION	0
CRUISE CONTROL (NO)	0		0
REAR PARKING SENSORS (NO)	0		0
REAR VIEW CAMERA (NO)	0		0

IMAGES




WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	6	TIRES ARE IN AVERAGE CONDITION	0
SPARE TYRE (YES)	6	SPARE TYRE IS IN AVERAGE CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	6	WHEEL ALIGNMENT IS IN AVERAGE CONDITION.	0

IMAGES









HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	6	LH APRON IS IN AVERAGE CONDITION	0
RH APRON	6	RH APRON IS IN AVERAGE CONDITION	0
RADIATOR	6	RADIATOR IS IN AVERAGE CONDITION	0

WIRING	6	WIRING HARNESS IS IN AVERAGE CONDITION	0
BATTERY	8	BATTERY IS IN GOOD CONDITION	0
BRAKE FLUID LEVEL	8	BRAKE FLUID & LEVEL IS IN GOOD CONDITION	0
ENGINE OIL	6	ENGINE OIL IS IN AVERAGE CONDITION	0
COOLANT LEVEL	6	COOLANT LEVEL IS IN AVERAGE CONDITION	0
BRAKE & COOLANT HOSE PIPES	6	ALL HOSES/PIPES IS IN AVERAGE CONDITION	0
UNDERCARRIAGE	6	UNDERCARRIAGE IS IN AVERAGE CONDITION	0
EXHAUST SYSTEM	6	EXHAUST GAS IS IN AVERAGE CONDITION	0

IMAGES



Ordered by: Jalaluddin Hashmi | Inspected date: 2019-09-09

Order Id: 107745

Overall Score  **5/10**



1,38,403

 **EXTERIOR**

 **5/10**

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	6	LICENSE PLATE IS IN AVERAGE CONDITION.	0
HEAD LIGHTS	6	HEAD LIGHTS ARE WORKING IN AVERAGE CONDITION	0
GRILLE	6	GRILLE IS IN AVERAGE CONDITION	0
TURN SIGNAL	6	INDICATOR IS WORKING IN AVERAGE CONDITION	0
HOOD	6	HOOD IS IN AVERAGE CONDITION	0
PILLAR	6	LH PILLARS ARE IN AVERAGE CONDITION	0
FRONT WINDSHIELD	6	FRONT WINDSHIELD IS IN AVERAGE CONDITION	0
SIDE VIEW MIRRORS	6	LH SIDE VIEW MIRROR/ASSY IS IN AVERAGE CONDITION	0
LH FENDER	6	LH FENDER IS IN AVERAGE CONDITION	1800
LH FRONT DOOR	6	LH FRONT DOOR IS IN AVERAGE CONDITION	0
LH RUNNING BOARD	6	LH RUNNING BOARD IS IN AVERAGE CONDITION	0
REAR WINDSHIELD	6	REAR WINDSHIELD IS IN AVERAGE CONDITION	0
TAIL LIGHT	6	TAIL LIGHT IS WORKING IN AVERAGE CONDITION	0
RH QUARTER PANEL	6	RH QUARTER PANEL IS IN AVERAGE CONDITION	0
RH RUNNING BOARD	6	RH RUNNING BOARD IS IN AVERAGE CONDITION	0
BODY RUST	6	BODY RUST 25%-MINOR	0
ROOF (REGULAR)	6	ROOF IS IN AVERAGE CONDITION	0
		PAINT IS IN AVERAGE	

PAINT CONDITION	6	PAINT IS IN AVERAGE CONDITION	0
FRONT BUMPER	4	FRONT BUMPER SCRATCHED/DENTED/LOOSED- MINOR	1500
FOG LAMPS	0	FOG LAMPS DAMAGED	0
LH REAR DOOR	4	LH REAR DOOR DENTED/SCRATCHEDD-MINOR	1500
LH QUARTER PANEL	2	LH QUARTER PANEL DENTED/SCRATCHED-MAJOR	2000
FUEL LID	4	FUEL LID DENTED/SCRATCHEDD-MINOR	500
REAR BUMPER	4	REAR BUMPER SCRATCHED/DENTED/LOOSED- MINOR	1500

Ordered by: Jalaluddin Hashmi | Inspected date: 2019-09-09

Order Id: 107745

Overall Score



5/10



1,38,403



EXTERIOR (CONTINUED)





5/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TRUNK LID/TAIL GATE	4	TRUNK LID DENTED/SCRATCHED-MINOR	1500
LUGGAGE COMPARTMENT LIGHT	0	LUGGAGE COMPARTMENT LIGHT NOT AVAILABLE	0
RH REAR DOOR	4	RH REAR DOOR DENTED/SCRATCHED-MINOR	1500
RH FRONT DOOR	4	RH FRONT DOOR DENTED/SCRATCHED-MINOR	1500
RH FENDER	4	RH FENDER DENTED/SCRATCHED-MINOR	1500








IMAGES







 **NEED ATTENTION** 





DOCUMENTS



DESCRIPTION

Petro-CNG car, Major dent & scratches, overall Average condition

Ordered by: Jalaluddin Hashmi | Inspected date: 2019-09-09

Order Id: 107745

Overall Score





5/10






1,38,403

IMAGES (75)







Ordered by: Jalaluddin Hashmi | Inspected date: 2019-09-09

Order Id: 107745

Overall Score



5/10



1,38,403

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.