


ECO INSPECTION CERTIFICATE

Premium

Order ID : 122618

121 Points Vehicle Inspection Certificate

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered By : Sunny .	Inspection Date : 2019-11-26	Location : LUDHIANA	Inspected By  Pawan Kumar Gupta
-------------------------	---------------------------------	------------------------	--

8/10

Overall Score

- ✓ Evaluated across 5 segments
- ✓ Covered 121+ checkpoints
- ✓ 121 does not need attention
- ✓ 1 Owner , 0 Years Vehicle Age
- ✓ No Accidental History

- ✓ Verified Technician
- 509+ vehicle inspected
- 1+ years experience

Maruti Suzuki Swift VDI AMT, 2019



VEHICLE INFORMATION

MAKE	MARUTI SUZUKI	ENGINE NUMBER	0786443
MODEL	SWIFT	REGISTRATION NO.	PB784456
MFG. DATE	01/2019	VIN/CHASSIS NUMBER	MBHCZC03SKA345345
TRIM	VDI AMT	ODOMETER READING	2559
COLOR	WHITE	INSURANCE EXPIRY	2019-10-1
BODY TYPE	HATCHBACK	VEHICLE PASSING	PRIVATE
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE SOUND

KEY HIGHLIGHTS

FLOOD DAMAGE	NO	MAJOR ACCIDENT(S)	NO	SERVICE LOGS AVAILABLE	NO
TYRE LIFE REMAINING (KM)	15,000	RC COPY AVAILABLE	ORIGINAL	BANK HYPOTHECATION	NOT APPLICABLE
DENT	NO	INSURANCE COPY AVAILABLE	NO	BANK NOC	NO



Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Price for this vehicle comes to be:

6,99,687




Very Good Condition

ECO SCORE & REPAIR COST ESTIMATE

ECO SCORE

Interior	<div style="width: 80%;"></div>	8 / 10
Wheel	<div style="width: 80%;"></div>	8 / 10
Test Drive	<div style="width: 80%;"></div>	8 / 10
Exterior	<div style="width: 80%;"></div>	8 / 10
Hood	<div style="width: 80%;"></div>	8 / 10

TOTAL ESTIMATE SPEND 0



Ordered by: Sunny . | Inspected date: 2019-11-26

Order Id: 122618

Overall Score



8/10



6,99,687



INTERIOR




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
DOOR PANEL	8	BOTH DOOR'S PANELS ARE IN GOOD CONDITION	0
DOOR HINGES	8	BOTH DOOR'S HINGES & LATCH ARE WORKING IN GOOD CONDITION	0
CARPET & FLOOR MAT	8	CARPET IS IN GOOD CONDITION	0
SEAT & SEAT BELT	8	SEATS/SEAT COVERS ARE IN GOOD CONDITION	0
DASHBOARD & INSTRUMENT PANEL	8	DASHBOARD/INSTRUMENT PANEL IS IN GOOD CONDITION	0
HORN	8	HORN SOUND IS IN GOOD CONDITION	0
SPEAKERS & MUSIC SYSTEM	8	SPEAKER'S SOUND IS IN GOOD CONDITION	0
HANDBRAKE	8	HAND BRAKE IS IN GOOD CONDITION	0
STEERING-MOUNTED CONTROLS	8	STEERING MOUNTED CONTROLS ARE WORKING IN GOOD CONDITION	0
PEDALS	8	ALL PEDAL'S BOOT IS IN GOOD CONDITION	0
CENTRAL LOCK	8	ALL DOOR'S LOCKS ARE WORKING IN GOOD CONDITION	0
A/C VENTS & HEATER	10	AC/HEATER IS WORKING AND COOLING/HEATING	0
CUP HOLDERS	8	CUP HOLDERS ARE IN GOOD CONDITION	0
NAVIGATION (YES)	8	NAVIGATION SYSTEM IS WORKING IN GOOD CONDITION	0
ODOMETER	8	ODOMETER IS WORKING IN GOOD CONDITION	0
POWER WINDOWS (YES)	8	ALL POWER WINDOWS ARE WORKING IN GOOD CONDITION	0

POWER WINDOWS (YES)	8	WORKING IN GOOD CONDITION	0
HAZARD LIGHT	8	HAZARD LIGHT IS WORKING IN GOOD CONDITION	0

 IMAGES



Ordered by: Sunny . | Inspected date: 2019-11-26

Order Id: 122618

Overall Score



8/10



6,99,687



TEST DRIVE




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
STEERING PERFORMANCE	8	STEERING WORKING IS IN GOOD CONDITION	0
BRAKE PERFORMANCE	8	BRAKES ARE WORKING IN GOOD CONDITION	0
CLUTCH PERFORMANCE	8	CLUTCH IS WORKING IS IN GOOD CONDITION	0
ENGINE NOISE	8	NO ANY ABNORMAL NOISE IN ENGINE	0
IGNITION SYSTEM	8	IGNITION SYSTEM IS WORKING IN GOOD CONDITION	0
SUSPENSION PERFORMANCE	8	SUSPENSION PERFORMANCE IS IN GOOD CONDITION	0
SUSPENSION FRONT SHOCKS	8	FRONT SUSPENSION IS WORKING IN GOOD CONDITION	0
SUSPENSION REAR SHOCKS	8	REAR SUSPENSION IS WORKING IN GOOD CONDITION	0
TRANSMISSION ENGAGE	8	TRANSMISSION IS WORKING IN GOOD CONDITION	0
CRUISE CONTROL (YES)	8	CRUISE CONTROL IS WORKING IN GOOD CONDITION	0
REAR PARKING SENSORS (YES)	8	REAR PARKING SENSOR IS WORKING IN GOOD CONDITION	0
REAR VIEW CAMERA (YES)	8	REAR VIEW CAMERA/DISPLAY IS WORKING IN GOOD CONDITION	0




IMAGES



WHEEL

8/10






INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
TYRES	8	TIRES ARE IN GOOD CONDITION	0
SPARE TYRE (YES)	8	SPARE TYRE IS IN GOOD CONDITION	0
WHEEL ASSEMBLY (STEEL RIM)	8	WHEEL ALIGNMENT IS IN GOOD CONDITION	0

 IMAGES

 HOOD

 8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LH APRON	8	LH APRON IS IN GOOD CONDITION	0
RH APRON	8	RH APRON IS IN GOOD CONDITION	0
RADIATOR	8	RADIATOR IS IN GOOD CONDITION	0
WIRING	8	WIRING HARNESS IS IN GOOD CONDITION	0
BATTERY	8	BATTERY IS IN GOOD CONDITION	0
BRAKE FLUID LEVEL	8	BRAKE FLUID & LEVEL IS IN GOOD CONDITION	0
ENGINE OIL	8	ENGINE OIL IS IN GOOD CONDITION	0
COOLANT LEVEL	8	COOLANT LEVEL IS IN GOOD CONDITION	0
BRAKE & COOLANT HOSE PIPES	8	ALL HOSES/PIPES IS IN GOOD CONDITION	0
UNDERCARRIAGE	8	UNDERCARRIAGE IS IN GOOD CONDITION	0
EXHAUST SYSTEM	8	NORMAL SMOKE	0

 IMAGES



Ordered by: Sunny . | Inspected date: 2019-11-26

Order Id: 122618

Overall Score



8/10



6,99,687

 EXTERIOR



8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
LICENSE PLATE	8	LICENSE PLATE IS IN GOOD CONDITION	0
FRONT BUMPER	8	FRONT BUMPER IS IN GOOD CONDITION	0
HEAD LIGHTS	8	HEAD LIGHTS ARE WORKING IN GOOD CONDITION	0
GRILLE	8	GRILLE IS IN GOOD CONDITION	0
TURN SIGNAL	8	INDICATOR IS WORKING IN GOOD CONDITION	0
FOG LAMPS	6	FOG LAMPS IS IN AVERAGE CONDITION	0
HOOD	8	HOOD IS IN GOOD CONDITION	0
PILLAR	8	LH PILLARS IS IN GOOD CONDITION	0
FRONT WINDSHIELD	8	FRONT WINDSHIELD IS IN GOOD CONDITION	0
SIDE VIEW MIRRORS	8	LH SIDE VIEW MIRROR/ASSY IS IN GOOD CONDITION	0
LH FENDER	8	LH FENDER IS IN GOOD CONDITION	0
LH FRONT DOOR	8	LH FRONT DOOR IS IN GOOD CONDITION	0
LH REAR DOOR	8	LH REAR DOOR IS IN GOOD CONDITION	0
LH RUNNING BOARD	8	LH RUNNING BOARD IS IN GOOD CONDITION	0
LH QUARTER PANEL	8	LH QUARTER PANEL IS IN GOOD CONDITION	0
FUEL LID	8	FUEL LID IS IN GOOD CONDITION	0
REAR WINDSHIELD	8	REAR WINDSHIELD IS IN GOOD CONDITION	0

REAR BUMPER	8	REAR BUMPER IS IN GOOD CONDITION	0
TAIL LIGHT	8	TAIL LIGHT IS WORKING IN GOOD CONDITION	0
TRUNK LID/TAIL GATE	8	TRUNK LID IS IN GOOD CONDITION	0
LUGGAGE COMPARTMENT LIGHT	8	LUGGAGE COMPARTMENT LIGHT IS WORKING IN GOOD CONDITION	0
RH QUARTER PANEL	8	RH QUARTER PANEL IS IN GOOD CONDITION	0
RH RUNNING BOARD	8	RH RUNNING BOARD IS IN GOOD CONDITION	0
RH REAR DOOR	8	RH REAR DOOR IS IN GOOD CONDITION	0

Ordered by: Sunny . | Inspected date: 2019-11-26

Order Id: 122618

Overall Score



8/10



6,99,687



EXTERIOR (CONTINUED)




8/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST. (RS)
RH FRONT DOOR	8	RH FRONT DOOR IS IN GOOD CONDITION	0
RH FENDER	8	RH FENDER IS IN GOOD CONDITION	0
BODY RUST	8	NO ANY BODY RUST	0
ROOF (REGULAR)	8	ROOF IS IN GOOD CONDITION	0
PAINT CONDITION	8	PAINT IS IN GOOD CONDITION	0



IMAGES





 DOCUMENTS



 DESCRIPTION

Excellent

Ordered by: Sunny . | Inspected date: 2019-11-26

Order Id: 122618

Overall Score





8/10



6,99,687

IMAGES (59)





Ordered by: Sunny . | Inspected date: 2019-11-26

Order Id: 122618

Overall Score



8/10



6,99,687

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.