INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification














Scientific





ECO INSPECTION REPORT

India's Most Comprehensive And Scientific Vehicle Inspection Service



Vehicle Information

Make Audi Transmission Type


Automatic

Model	RS e-tron	Registration Type	Private
Year	2021	Registration No.	DL10CG3657
Trim	GT	VIN/Chassis Number	16191
Exterior Color	Grey	Kms Run	15025
Interior Color	Beige	Manufacturing Date	2021-05-20
Body Type	Sedan	Registration Date	2021-07-15
Fuel Type	Electric	Insurance Expiry	2022-7-14
Motor No.	452390	Location	Janak Puri
Number of Owners	1	Motor Sound Link	Listen Engine Sound

Key Highlights

Flood Damage	Νο	Insurance Copy Available	Νο
Tyre Life Remaining (KM)	25,105	Service Logs Available	Νο
Dent	Yes	Bank Hypothecation	Νο
Major Accidents	Yes	Bank NOC	Νο
RC Copy Available	Yes (Original)		

ECO Repair Estimate





support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)

















Order ID : 20588 Generated : 12 Feb 2021

ECO OVERALL SCORE BREAKDOWN

Interior




Image: static display in the static display in the



Exterior



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 2/13










(a)



Order ID : 20588 Generated : 12 Feb 2021

EXTERIOR

Vehicle Exterior View and Condition



Front License Plate is available?	~
License Plates are HSRP complaint?	~
Head Lights are working?	~
Turn Signal lamps are working?	~
Hazard Lamps are working?	~

Rear License Plate is available?	~
HSRP colour sticker is available?	
Tail Lights are working?	~
Fog Lamps are working?	×
Break lights are working?	~



Rear windshield wiper is working in good condition?



Front windshield wiper is working in good condition?

Reverse parking lights are working?



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 3/13





G Unbiased Objective




G




Order ID : 20588 Generated : 12 Feb 2021


Exterior Images

FRONT VIEW





LEFT SIDE VIEW






RIGHT SIDE VIEW

LEFT FRONT CORNER VIEW



LEFT REAR CORNER VIEW



RIGHT FRONT CORNER VIEW



RIGHT REAR CORNER VIEW





support@eco.com





Page 4/13












Order ID : 20588 Generated : 12 Feb 2021

INTERIOR

Vehicle Interior View and Condition



Music System is working properly?	
Navigation System is working properly?	
Horn is loud & clear?	~
Sun Visors are working properly?	~
Luggage Compartment light is working properly?	N/A
Power Windows are working?	~
Carpets are in good condition?	~
Front Seat Belts are working properly?	N/A
Boot Lever is working properly?	~
Front De-Fogger is available?	~
USB port is available?	~
Rear view mirror is functional?	~
Passenger side seat adjustments are working properly?	? 🗸

Speakers are working properly?	~
Steering Mounted Controls are working properly?	N/A
Handbrake is working properly?	~
All Cabin lights are working properly?	N/A
Central Lock is working?	×
Floor Mats are available?	~
Seat Covers are in good condition?	~
Rear Seat Belts are working properly?	N/A
Fuel Lid Lever is working properly?	~
Bonnet Lever is working properly?	~
Rear De-Fogger is available?	~
Glove box light is working?	~
Driver side seat adjustments are working properly?	~







support@eco.com













G Objective Comprehensive

G





Order ID : 20588 Generated : 12 Feb 2021

Interior Images


DASHBOARD VIEW




CLUSTER METER VIEW



FRONT SEATS





GLOVE BOX




INTERIOR REAR VIEW



INTERIOR FRONT VIEW



INTERIOR DOOR PANEL





support@eco.com





Page 6/13





C Comprehensive Objective




G




Order ID : 20588 Generated : 12 Feb 2021

WHEELS

Wheel View and Condition



LEFT FRONT TYRE







support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 7/13






ELECTRIC VEHICLE BATTERY, CHASSIS AND PERFORMANCE


C

Objective


(A)

Comprehensive





State of Charge (SoC) before Test Drive	85%
State of Charge (SoC) AfterTest Drive	75%
Battery Temperature	48 c
Battery Capacity	25 kwH
Test Drive Distance	5 Km
Average Discharge per Km Driven	2%






support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 8/13



Images

VIN/CHASSIS NUMBER





Documents

REGISTRATION CERTIFICATE



	INDIA me #: 9741474849	Cover Note #			Geographic		ight On 18/03/2017	23:59:59
Insured Motor Vehic	le Details & Premium C							
Registration Mark &	Year of Manuf.	Type of Body	cc	Coverage	IDV in Rs.	Engin	ne No.	Seating Ca
No.	rear on warran.	Metallic	Metallic		itory interns.	3800	3800222	
KA41N2842	2010	Make of Vehicle	796	796 Package 120861.00		Chass	sis No.	5
NA41192042	2010	MARUTI ALTO LXI	/30	Package	120801.00	1585	9589	
Registration Authori	tv							
Vehicle	Trailer	Non Electrical Access.	Elec./Elect. /	ACC.	Bi-Fuel Kit	Total Value	Net Premiur	n Rs.
120861.00	0.00	0.00	0.00		0.00	120861.00	3295.92	
	A, Own Da	amage Premium(Rs.)				B. Third Party Premiu	m(Rs.)	
lectrical Accessories (i Fuel Kit (IMT 25) dd: alles (IMT 31)	(IMT 24)		0.0	Add:	IMT 25)		_	
ioreign Vehicle Loadin Beographical Area Ext Trailers (IMT 30)		5	AM	PA Owner P	osl Rs 200000			
oreign Vehicle Loadin leographical Area Ext railers (IMT 30) dditional Loading ess: roturtary Excess Less roti Theft Device (IMT utomobile Association landicap Discount (IM lehicle Use (IMT 13)	ension (MT 1) 0% (MT 22A) 10) 101 B)	S	0.0 -89.21 0.0 0.00 0.00	Less: China Party F Less: Third Party F Limit of Liable	31)	20)		
oreign Vehicle Loadin teographical Area Ext railers (IMT 30) dditional Loading ess: foluntary Excess Less viti Theft Device (IMT utomobile Association tandicap Discount (IM fehicle Use (IMT 13) to Claim Discount	ension (MT 1) 0% (MT 22A) 10) 1(MT 8) T 12)	(50%)	0.0 -89.21 0.0 0.0 0.0 0.0 1939.3	Aalies (IMT PA Owner P D O	31) est Rs 200000 al Area Extension (IMT Property Damage (IMT : Illy Under Section II-I (I	20)		
oreign Vehicle Loadin leographical Area Ext railers (IMT 30) dditional Loading ess: ofuntary Excess Less ntl Theft Device (IMT utomobile Association landicap Discount (IM ehicle Use (IMT 13) to Claim Discount ny Other Loading Dis	ension (MT 1) 0% (MT 22A) 10) 1(MT 8) T 12)		0.0 -89.21 0.0 0.00 -1939.30 -678.75	Aalies (IMT PA Owner P Georgenes IMT 15 Less: Third Party F Limit of Liable Child Party F Limit of Liable	31) est Rs 200000 al Area Extension (IMT Property Damage (IMT :	20)		
dditional Loadin eographical Area Extra railers (IMT 30) dditional Loading ess: oluntary Excess Less nti Theft Device (IMT utomobile Association andicap Discount (IM ehicle Use (IMT 13) o Claim Discount ry Other Loading/Dis	ension (MT 1) 0% (MT 22A) 10) 1(MT 8) T 12)	(50%) (-35%)	0.0 -89.2 0.0 0.0 -1939.3 -678.7 1200.5	Aalies (IMT PA Owner P D Owner P Own	31) est Rs 200000 al Area Extension (IMT Property Damage (IMT : Illy Under Section II-I (I	20)		
dditional Loading eggraphical Area Ext railers (IMT 30) dditional Loading ess: oluntary Excess Less nti Theft Device (IMT utomobile Association andicap Discount (IM ehicle Use (IMT 13) o Claim Discount ny Other Loading Dis	ension (MT 1) 0% (MT 22A) 10) 1(MT 8) T 12)	(50%) (-35%) Agent (No Co	0.0 -89.21 0.0 0.00 -1939.30 -678.75	Aalies (IMT PA Owner D Company D MT 15 Less: Third Party F Limit of Liab Company A Limit of Liab Company A Liab Company A Limit of Liab Company A Limit of Liab Company A Liab Company A Limit of Liab Company A Liab Company A Liab	31) The Property Damage (IMT - Property Damage (IMT - IIII) Under Section II-I (I pading Discount am (A + B) Tax (402.99)+Swachh	20)) 750000		Rs. 1

INSURANCE COPY



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)













G

C






Order ID : 20588 Generated : 12 Feb 2021

NEED ATTENTION

Interior





Remarks Central Lock Not Working

Repair Estimate ₹600







Power Window Not Working


Repair Estimate ₹600

Remarks

Wheel


FRONT TYRES


SPARE TYRES











Repaired: Color Mismatched, Color faded, Visible dent, Misaligned



www.droom.in/eco

support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 10/13







Objective Comprehensive

G

G





Generated : 12 Feb 2021 Order ID : 20588

Other Images

GRILLE



FRONT BUMPER



REAR BUMPER



BONNET HOOD



FRONT WINDSHIELD



REAR WINDSHIELD





LEFT FENDER



RIGHT FENDER



LEFT QUARTER PANEL





support@eco.com











Unbiased

G G Comprehensive Objective






Order ID : 20588 Generated : 12 Feb 2021

Other Images

RIGHT QUARTER PANEL



BOOT TRUNK LID







FRONT LICENSE PLATE



CEED **APLE** RS m-tr 0 0

REAR LICENSE PLATE





POWER WINDOWS



REAR VIEW MIRROR



ENGINE COMPARTMENT



UNDERCARRIAGE



BATTERY



TRUNK LID





support@eco.com





Page 12/13











Order ID : 20588 Generated : 15 Jul 2022

Other Images

MIL/ENGINE LIGHT



Overall Comments

Car is in average condition

Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology limited. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the

mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.



support@eco.com

Contact No. - 9650 08 08 08 (Toll Free)



Page 13/13









www.droom.in/eco