

# ECO INSPECTION REPORT

Basic

Order ID : 19115

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.

Ordered by : Deep Gupta

Inspection Date : 2018-02-17

8/10



Overall Score

- ✓ Evaluated across 6 segments
- ✓ 1 owner , 3 Years Vehicle Age
- ✓ No Accidental History

Inspected By



✓ Verified Technician

200+ vehicle inspected

2+ years experience

Yunus Guttedar

## Bajaj Pulsar 180cc, 2015



### VEHICLE INFORMATION

MAKE	BAJAJ	REGISTRATION NO	MH12LS1953
MODEL	PULSAR	VIN/CHASIS NUMBER	30003
YEAR	2015	KMS RUN	11833
TRIM	180CC	INSURANCE EXPIRY	2018-2-17
COLOR	OTHER	LOCATION	PUNE
FUEL TYPE	PETROL	ENGINE SOUND LINK	NIL

### KEY HIGHLIGHTS







 FLOOD DAMAGE	NO	 MAJOR ACCIDENT(S)	NO	 SERVICE LOGS AVAILABLE	NO
 TYRE LIFE REMAINING (KM)	65	 RC COPY AVAILABLE	YES (ORIGINAL)	 BANK HYPOTHECATION	NO
 DENT	NO	 INSURANCE COPY AVAILABLE	NO	 BANK NOC	NO

### ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT

#### ECO SCORE

 Tire	<div><div></div></div>	8 / 10
 Control	<div><div></div></div>	7 / 10
 Light	<div><div></div></div>	8 / 10
 Oil	<div><div></div></div>	8 / 10
 Chassis	<div><div></div></div>	9 / 10
 Stand	<div><div></div></div>	7 / 10

#### ECO COMMENTS

 Tire	N/A
 Control	N/A
 Light	N/A
 Oil	N/A
 Chassis	N/A
 Stand	N/A

### DESCRIPTION

good condition



Ordered by: Deep gupta | Inspected date: 2018-02-17

Order Id: 19115

Overall Score



**8/10**



**IMAGES**





Ordered by: Deep gupta | Inspected date: 2018-02-17

Order Id: 19115

Overall Score



8/10



## DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE