

INDIA'S MOST TRUSTWORTHY AUTO INSPECTION & VERIFICATION SERVICE



AI & Tech Driven Inspection & Certification



Independent



Unbiased



Objective



Comprehensive



Scientific

- a service by **droom**

Odometer Assurance Report

Checking Probability of Odometer Tampering

Ordered By



Anant Goel



23 / 11 / 2020

Inspected By



Mitesh Karwa



Verified Technician



36+ Vehicle Treated



4+ Years Experience

Vehicle Details



Make	Hyundai
Model	EON
Year	2015
Trim	ERA +
Registration No.	DL10CG3657

Certification Fail Criteria

This is to inform that the following vehicle has undergone expert check for Odometer tampering and it has been found that the Odometer might be tampered and the probability if odometer being tempered is 5 %

Service Logs and Tags

- ✓ The digits on the odometer are misaligned and indicates a probability of odometer tampering
- ✓ Presence of extra switch below the car dashboard and indicates a probability of odometer tampering
- ✓ Kilometers driven by the vehicle since date of registration is less than monthly average and indicates a probability of tampering

Expert Eye Check

- ✓ Kilometers driven by the vehicle since date of registration is less than the monthly average of CNG/Diesel vehicles and indicates a probability of tampering
- ✓ Although the distance travelled by vehicle is less than 25K Kilometers, original factory fitted tires were not found on the vehicle indicating a probability of tampering
- ✓ Unavailability of service logs

Images



Kilometers Driven

- ✓ Kilometers driven by the vehicle based on the last service log is less than monthly average thus indicating possibility of odometer tampering
- ✓ Kilometers driven by the vehicle is less than the kilometers mentioned in the last service log available

Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology limited. This report was generated based on the request raised by the customer, and ECO will not be responsible for any loss incurred by the customer relying on the odometer inspection report.

The data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts.



www.droom.in/eco