

# ECO INSPECTION REPORT

121+ Checkpoints Doorstep Inspection Service

**Ordered By**

Anant Goel

10 / 01 / 2021

Gurgaon

**Inspected By**

Mitesh Karwa

- Verified Technician
- 36+ Vehicle Treated
- 4+ Years Experience

**Audi A4 Premium Plus, 2019**

Overall Score

₹ 34,07,519

Automobile from individual in good condition is valued


## Vehicle Information

Make	Audi	Transmission Type	Automatic
Model	A4	Registration No.	DL10CG3657
Year	2019	VIN/Chassis Number	16191
Trim	Premium Plus	Kms Run	25105
Color	Terra Gray	Insurance Expiry	2020-7-14
Body Type	Sedan	Location	Janak Puri
Fuel Type	Petrol	Engine Sound Link	<a href="#">Listen Engine Sound</a>

## Key Highlights


Flood Damage	No	Insurance Copy Available	No
Tyre Life Remaining (KM)	25,105	Service Logs Available	No
Dent	Yes	Bank Hypothecation	No
Major Accidents	No	Bank NOC	No
RC Copy Available	Yes (Original)		

## ECO Repair Estimate



# EXTERIOR

## Vehicle Exterior View and Condition



Front License Plate is available?	✓
License Plates are HSRP complaint?	✗
Head Lights are working?	✓
Turn Signal lamps are working?	✗
Hazard Lamps are working?	✓
License plate light is working?	✓
Rear windshield wiper is working in good condition?	✓

Rear License Plate is available?	✓
HSRP colour sticker is available?	✗
Tail Lights are working?	✓
Fog Lamps are working?	N/A
Break lights are working?	✓
Front windshield wiper is working in good condition?	✓
Reverse parking lights are working?	✓



## Exterior Images

FRONT VIEW



REAR VIEW



LEFT SIDE VIEW



RIGHT SIDE VIEW



LEFT FRONT CORNER VIEW



LEFT REAR CORNER VIEW



RIGHT FRONT CORNER VIEW



RIGHT REAR CORNER VIEW



# INTERIOR

## Vehicle Interior View and Condition

0 Critical
 2 Bad
 4 Below Average
 6 Average
 8 Good
 10 Excellent

Rear View Camera <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">6</span>	Ceiling <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">8</span>
Rear Parking Sensors <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">10</span>	Dashboard & Instrument Panel <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">8</span>
Door Hinges <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">0</span>	Odometer <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">10</span>
Front LH Door Panel <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">8</span>	Front RH Door Panel <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">8</span>
Air Conditioning System <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">8</span>	Heating System <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">6</span>
Rear LH Door Panel <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">4</span>	Pedals <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">8</span>
	Rear RH Door Panel <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">4</span>

Music System is working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>	Speakers are working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
Navigation System is working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✗</span>	Steering Mounted Controls are working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">N/A</span>
Horn is loud & clear? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>	Handbrake is working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
Sun Visors are working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✗</span>	All Cabin lights are working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">N/A</span>
Luggage Compartment light is working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">N/A</span>	Central Lock is working? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
Power Windows are working? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>	Floor Mats are available? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
Carpets are in good condition? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>	Seat Covers are in good condition? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
Seat Belts are working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">N/A</span>	Fuel Lid Lever is working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
Boot Lever is working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✗</span>	Bonnet Lever is working properly? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✗</span>
Front De-Fogger is available? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>	Rear De-Fogger is available? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
USB port is available? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>	Glove box light is working? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>
Rear view mirror is functional? <span style="float: right; border: 1px solid black; border-radius: 50%; padding: 2px 5px;">✓</span>	



## Interior Images

DASHBOARD VIEW



CLUSTER METER VIEW



FRONT SEATS



REAR SEATS



GLOVE BOX



INTERIOR REAR VIEW



INTERIOR FRONT VIEW




INTERIOR DOOR PANEL







# WHEELS

Wheel View and Condition




## Wheels Images




# TEST DRIVE

Test Drive and Condition





# HOOD

Vehicle Hood View and Condition




# Hood Images



### Miscellaneous

Service Required?	✓	Cruise Control?	✓
VIN/Chassis Number matching with document?	✗	Medical Kit available?	✗
Vehicle jack and wrench available?	✓		


### Images



### Hygiene & Cleanliness

Car odour?	✓	Door panel, seat pockets and cup holders are clean?	✓
Seat covers are clean & tidy?	✗	Mirrors and windshield are clean?	✗
Floor mats are clean?	✓	Floor & underseats are clen?	✓

### Documents





# NEED ATTENTION

## Interior

CENTRAL LOCK



Remarks: Central Lock Not Working  
Repair Estimate: ₹ 600

POWER WINDOW



Remarks: Central Lock Not Working  
Repair Estimate: ₹ 600

## Wheel

FRONT TYRES



Remarks: Spare tyres are not in a good condition  
Repair Estimate: ₹ 600

SPARE TYRES



Remarks: Spare tyres are not in a good condition  
Repair Estimate: ₹ 600

## Exterior

FOG LAMPS



Remarks: Major cracks in Fog Lamps  
Repair Estimate: ₹ 900

LEFT FRONT DOOR



Remarks: Scratches/Dents in Front Door  
Repair Estimate: ₹ 900



## All Images


GRILLE



FRONT BUMPER



REAR BUMPER



BONNET HOOD



FRONT WINDSHIELD



REAR WINDSHIELD



LEFT SIDE MIRROR



RIGHT SIDE MIRROR



LH FRONT DOOR



RIGHT FRONT DOOR



LEFT REAR DOOR




RIGHT REAR DOOR



LEFT FENDER



RIGHT FENDER



LEFT QUARTER PANEL





## Disclaimer

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

SAMPLE

