





Vehicle History Certificate (1 of 3)



VEHICLE HISTORY PLATINUM REPORT

FEBRUARY 7TH, 2018

MAHINDRA, XUV500, Delhi

Summary	
Registration Number	DL12CA3603
Brand	MAHINDRA
Model	XUV500
Vehicle Age	6 years and 1 months.



Registration Details	
State Code	DL
RTO Code	12
Chassis Number	MA1YL2HJUC6L****2
Vehicle Type	L.M.V. (CAR)
City	North Delhi
State	Delhi

Vehicle Details	, gtol'
Exterior Color	Silver
Cubic Capacity	2179cc
Number of Seats	7
Number of Cylinder	4
Weight	1785 Kg
Horse Power	141 @ 3800 RPM
Wheel Base	2700 mm
Interior Color	Beige

Insurance Details	
Insurance Upto	4 October, 2017
Insurance Type	Comprehensive
Insurance Company	United Insurance Co

Hypothecation Details	
Financier Name	HDFC Bank Ltd
Hypothecation Type	НТ



Service Logs	
Service Dealer Name	MAHINDRA Shiva Auto Cars India Pvt Ltd.
No. of Times Vehicle Serviced	8
Last Service Date	20 December, 2017
Latest Odometer Reading	62936

Purchase Details	
Order Date	19 July, 2012
Invoice Date	26 July, 2012
Delivery Note Date	26 July, 2012
Invoice Amount (Rs.)	16,28,915.00

Blacklist Details	184.
Blacklisted (Yes/No)	The blacklist details of this vehicle is not available

Disclaimer

Droom History report is a proprietary asset of Droom Technology Private. Limited. (Droom). Copying, sharing, transmission and selling of this report / information in any form is illegal and strictly prohibited. Droom has gathered this information / data from its partners and third parties and shall not be liable for any mismatch, error and/or recency in data nor does it claim authenticity of the same in any manner whatsoever. All the reports containing the information / data is only for the selective areas or purposes only and some information / facts might not available as per the availability of the data / information but Our partners shall be liable for sourcing the data in strict adherence with all relevant laws. The purpose of this report is solely to keep the buyer informed about the background history of used vehicle before buying.



OBV Pricing Certificate (2 of 3)



India's First & Only Algorithmic Pricing Engine for Used Automobiles



UNBIASED





Rajesh Singh

babusingh.8945@gmail.com

Order ID: 104418

07 Feb 2018



Automobile from individual in good condition is valued at

Rs. 8,27,425 - Rs. 8,78,606

Mahindra Xuv500 2012 W8



A 62,000



2012

Vehicle Price in All Conditions



FAIR

Rs.8,06,739 - Rs.8,56,641



VERY GOOD

Rs.8,48,110 - Rs.9,00,570



EXCELLENT

Rs.8,68,796 - Rs.9,22,536

Vehicle Details

Make

Mahindra

Model

Xuv500

Year

2012

Trim

W8

KM Driven

62,000 kms

City

Ghaziabad

Owner

One

Accident

None

Color

Silver

Advanced Evaluation Conditions

GOOD

Transmission, Suspension, Steering, Frame, Engine, Electrical, Car Interior, Car Exterior, Brakes, AC

Disclaimer

The Orange Book Value or any pricing or valuation mentioned in the report is an indicative pricing, generated based on proprietary patented methodology of Droom and/ or its affiliates/partners/subsidiaries. The actual price of the vehicle/ mobile device may vary based on actual condition of the vehicle/ mobile device and several other parameters. Droom cannot be held responsible for any losses incurred or liabilities arising by the party relying on this report.















Rajesh Singh

babusingh.8945@gmail.com

Order ID: 104418

07 Feb 2018





Rs. 16,63,012



Rs. 8,29,085



Rs. 7,57,500



Rating & Review

Rakesh Singh ★★★★★

Mahindra XUV model has the ability to do 0-100kph in just 12.77 seconds. This gives it a similar time to the diesel powered car. However, this car has a lot more torque steer. Another big problem is the suffering fuel economy. The car rarely crossed double digits – not good when you consider the increasing price of petrol. In terms of features, the car is well equipped. The car has dual airbags, ESP and other safety electronics. The Mahindra offers ride quality that is similar to what we have seen before. It is a bit bumpy at low speeds but gets better with speed. While it does have a bit of movement the car does feel decently composed. The car also can take corners at decent speeds. The car is well-liked in the country and majority buyers have opted for the diesel motor. Even though Mahindra is selling the car in India, it is mainly developed and produced for export markets.

Disclaimer

The Orange Book Value or any pricing or valuation mentioned in the report is an indicative pricing, generated based on proprietary patented methodology of Droom and/ or its affiliates/partners/subsidiaries. The actual price of the vehicle/ mobile device may vary based on actual condition of the vehicle/ mobile device and several other parameters. Droom cannot be held responsible for any losses incurred or liabilities arising by the party relying on this report.













0k



Rajesh Singh

babusingh.8945@gmail.com

Order ID: 104418

07 Feb 2018



Mean

Median

High

Similar Listings for Past 90 Days






Low



Similar Listings for Lifetime



Similar Orders for Lifetime



Disclaimer

The Orange Book Value or any pricing or valuation mentioned in the report is an indicative pricing, generated based on proprietary patented methodology of Droom and/ or its affiliates/partners/subsidiaries. The actual price of the vehicle/ mobile device may vary based on actual condition of the vehicle/ mobile device and several other parameters. Droom cannot be held responsible for any losses incurred or liabilities arising by the party relying on this report.















Rajesh Singh

babusingh.8945@gmail.com

Order ID: 104418

07 Feb 2018

Component Health Check

A vehicle undergoes enormous wear and tear with time. It is often imperative to inspect and replace parts of the vehicle on a timely basis to keep it in prime condition. These aspects often go unnoticed and become real pain points with time. Use the Component Health Check for maintaining your vehicle components without any hassles. It would provide the list of parts to be inspected every subsequent year based on their age to help you find out the parts needing replacement.



*This is a suggestive list and is not based on the actual physical inspection of this vehicle

Disclaimer

The Orange Book Value or any pricing or valuation mentioned in the report is an indicative pricing, generated based on proprietary patented methodology of Droom and/ or its affiliates/partners/subsidiaries. The actual price of the vehicle/ mobile device may vary based on actual condition of the vehicle/ mobile device and several other parameters. Droom cannot be held responsible for any losses incurred or liabilities arising by the party relying on this report.







India's First & Only Algorithmic Pricing Engine for Used Automobiles









Rajesh Singh Order ID: 104418

babusingh.8945@gmail.com

07 Feb 2018

Glossary

New Vehicle Price Now: This provides the current On-Road Price of a new vehicle of the same Make-Model-Trim **New Vehicle Price Then:** This provides the On-Road Price of the vehicle at the time it was purchased in brand new condition.

Total Cost of Ownership: This provides the total cost of owning this vehicle which includes the cost of running this vehicle and its maintenance cost over the next 5 years

What Others Paid: This provides an estimated value of the price paid by others for a similar used vehicle. However, the final valuation provided might vary based on the city, condition of the car and many other factors.

Next 3 Year Depreciation of the Vehicle: This provides an estimated price that your used vehicle would fetch or an estimated price that you would have to pay for a similar vehicle over the next 3 years.

Similar Listings for Past 60 days/Past 90 days/Lifetime: This provides some data points regarding similar vehicles that have been listed on Droom in the respective duration. Low and High provide the Lowest and the Highest Values Quoted for similar vehicles whereas Mean and Median indicate the average and median values.

Similar Orders for Past 60 days/Past 90 days/Lifetime: This provides some data points regarding similar vehicles that have been sold on Droom in the respective duration. Low and High provide the Lowest and the Highest Values at which similar vehicles have been sold whereas Mean and Median indicate the average and median values.

Component Health Check: This provides a list of parts that are advised to be inspected every subsequent year based on their age. This would help you find out the parts needing maintenance/replacement.

Disclaimer

The Orange Book Value or any pricing or valuation mentioned in the report is an indicative pricing, generated based on proprietary patented methodology of Droom and/ or its affiliates/partners/subsidiaries. The actual price of the vehicle/ mobile device may vary based on actual condition of the vehicle/ mobile device and several other parameters. Droom cannot be held responsible for any losses incurred or liabilities arising by the party relying on this report.





ECO Inspection Certificate (3 of 3)













ECO INSPECTION REPORT

Premium

Order ID: 19086

ECO Inspection report is based on information received during physical inspection performed using ECO's proprietary methodology by trained and verified technicians. ECO inspection checklist is mutually exclusive and collectively exhaustive covering all the important points needed in verifying or inspecting a vehicle.





Mahindra Xuv500 W8, 2012



VEHICLE INFORMATION

MAKE	MAHINDRA	TRANSMISSION TYPE	MANUAL
MODEL	XUV500	REGISTRATION NO	DL12CA3603
YEAR	2012	VIN/CHASIS NUMBER	11972
TRIM	W8	KMS RUN	62936
COLOR	SILVER	INSURANCE EXPIRY	2017-10-4
BODY TYPE	SUV	LOCATION	GHAZIABAD
FUEL TYPE	DIESEL	ENGINE SOUND LINK	LISTEN ENGINE

KEY HIGHLIGHTS




Orange Book Value, a service by Droom is India's Only Algorithmic pricing engine. With this evaluation, the Fair Market Value for this vehicle comes to be:

Good Condition

8,88,151

ECO SCORE & OPTIONAL SPEND ESTIMATE FOR GOOD TO GREAT







Order Id: 19086

Ordered by: Rajesh Singh | Inspected date: 2018-02-09

6/10



8,88,151

O DOES NOT NEED ATTENTION

NEED ATTENTION

GUE INTERIOR

Overall Score

7/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
DOOR PANEL	7	GOOD	0
DOOR HINGES	7	GOOD	0
CARPET & FLOOR MAT	6	GOOD	0
SEAT & SEAT BELT	7	GOOD	0
DASHBOARD & INSTRUMENT PANEL	7	GOOD	0
HORN	7	GOOD	0
SPEAKERS & MUSIC SYSTEM	7	GOOD	0
STEERING-MOUNTED CONTROLS	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
PEDALS	6	GOOD	0
A/C VENTS & HEATER	7	GOOD	0
CUP HOLDERS	7	GOOD	0
NAVIGATION	7	GOOD	0
POWER WINDOWS (YES)	7	GOOD	0
HAZARD LIGHT	7	GOOD	0

WHEEL

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
TYRES	6	GOOD	0
WHEEL ASSEMBLY (ALLOY RIM)	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
SPARE TYRE	5	GOOD	0





Order Id: 19086

Ordered by: Rajesh Singh | Inspected date: 2018-02-09

6/10



8,88,151

O DOES NOT NEED ATTENTION

NEED ATTENTION

₹ TEST DRIVE

Overall Score

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
BRAKE PERFORMANCE	6	GOOD	0
CLUTCH PERFORMANCE	6	GOOD	0
ENGINE NOISE	6	GOOD	0
IGNITION SYSTEM	6	GOOD	0
SUSPENSION FRONT SHOCKS	6	GOOD	0
SUSPENSION REAR SHOCKS	6	GOOD	0
TRANSMISSION ENGAGE	6	GOOD	0
CRUISE CONTROL	6	GOOD	0
REAR PARKING SENSORS	7	GOOD	0
STEERING PERFORMANCE	5	MINOR SOUND	0
SUSPENSION PERFORMANCE	5	GOOD	0
REAR VIEW CAMERA	0	NO	0

¥ HOOD

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LH APRON	7	GOOD	0
RH APRON	7	GOOD	0
RADIATOR	6	GOOD	0
WIRING	7	GOOD	0
BATTERY	6	GOOD	0
BRAKE FLUID LEVEL	6	GOOD	0
BRAKE & COOLANT HOSE PIPES	6	GOOD	0
UNDERCARRIAGE	7	GOOD	0







Order Id: 19086

Ordered by: Rajesh Singh | Inspected date: 2018-02-09

Overall Score 6/10



8,88,151

O DOES NOT NEED ATTENTION

NEED ATTENTION

HOOD (CONTINUED)

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
EXHAUST SYSTEM	7	GOOD	0
CENTRAL LOCK	7	GOOD	0
ENGINE SOUND	0		0
ENGINE OIL	5	GOOD	0
COOLANT LEVEL	5	GOOD	0

EXTERIOR

6/10

INSPECTION CHECKPOINTS	SCORE(X/10)	REMARKS/COMMENTS	OPTIONAL SPEND EST(RS)
LICENSE PLATE	7	GOOD	0
FRONT BUMPER	6	MINOR PAINTED	0
HEAD LIGHTS	7	GOOD	0
GRILLE	6	GOOD	0
TURN SIGNAL	7	GOOD	0
HOOD	6	MINOR SCRETCH	0
FRONT WINDSHIELD	7	GOOD	0
LH REAR DOOR	6	MINOR SCRETCH	0
LH RUNNING BOARD	7	GOOD	0
LH QUARTER PANEL	7	GOOD	0
FUEL LID	7	GOOD	0
REAR WINDSHIELD	6	MINOR SCRETCH	0
REAR BUMPER	7	GOOD	0
TAIL LIGHT	7	GOOD	0





Ordered by: Rajesh Singh | Inspected date: 2018-02-09

Order Id: 19086

Overall Score





8,88,151



6/10



MAGES







































Order Id: 19086 Ordered by: Rajesh Singh | Inspected date: 2018-02-09

Overall Score

6/10

8,88,151

O DOES NOT NEED ATTENTION

NEED ATTENTION



DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the vehicle.

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.

DISCLAIMER

This inspection report was generated by ECO, a service arm of Droom Technology Pvt Ltd. This report was generated based on the request raised by the party, whom the report is addressed to, for the stated purpose only. ECO will not be responsible for any loss incurred by the party relying on the inspection report.

All data presented in the report are based on the facts at the time of inspection and ECO cannot be held responsible for any discrepancy in the mentioned facts. ECO has not validated the authenticity of the odometer reading and is not responsible for any tampering performed by the current owner of the

Ownership documents of the vehicle were verified by the technician performing the auto inspection. However, ECO is not responsible for validating the authenticity of the document.



